	FMP Tier 1	Projects Buil		ounds	
School Site	Project	Estimated Cost	Funding Source	Notes	Status
Arboga Elementary	Compliant labeling of electrical panels/mechanical panels.	\$ 1,500.00	RRMA	Hazard stickers included with District arc flash study. All other required labels are at an added cost.	In Progress
Arboga Elementary Arboga Elementary	Drinking fountains. Lead paint remediation as needed (analysis needed).	\$ 8,000.00 \$ 9,000.00	DM DM	Received estimate. Received estimate.	Spring/Summer 2019 Ongoing
Arboga Elementary	Parking lot re-striping.	\$ 7,000.00	TBD	ADA striping completed summer 2016; sealing of asphalt needed as well.	Spring/Summer 2018
Cedar Lane Elementary	Roofing.	\$ 160,000.00	TBD	Site undergoing roof assessment. Work will be scheduled after results.	In Progress
Cordua Elementary	Compliant labeling of electrical panels/mechanical panels.	\$ 1,500.00	RRMA	Hazard stickers included with District arc flash study. All other required labels are at an added cost.	In Progress
Covillaud Elementary	Remove VAT tiles.	\$ 16,000.00	DM	This is an ongoing process. We removed VAT tiles in the main wing.	Ongoing
District Support	Drainage throughout.	\$ -	RRMA	We are addressing issues as they arise.	Ongoing
Dobbins Elementary	Water testing and compliance (with remediation to be determined).	\$ 44,000.00	RRMA	Installed phosphorus system.	
Ella Elementary	Compliant labeling of electrical panels/mechanical panels.	\$ 1,500.00	RRMA	Hazard stickers included with District arc flash study. All other required labels are at	Testing Is Ongoing
Ella Elementary	Water penetrationdry rot noted.	\$ 90,000.00	DM	an added cost. Dry rot in several locations. Needs repair then site will be painted.	In Progress
Foothill Intermediate	Verify science safety and student equipment.	\$ -	TBD	Waiting on further direction from site.	In Progress Pending
oothill intermediate	Install automatic irrigation filter system.		TBD	Getting estimates.	In Progress
Foothill Intermediate	Water testing and compliance (with remediation to be determined).	\$	RRMA	Installed phosphorus system. Testing will be ongoing quarterly	Ongoing
Johnson Park Elementary	Landscape outside cafeteria area.	\$ 9,000.00	RRMA	Getting estimates.	In Progress
Cynoch Elementary	Compliant labeling of electrical panels/mechanical panels.	\$ 1,500.00	RRMA	Hazard stickers included with District arc flash study. All other required labels are at an added cost	Ongoing
Kynoch Elementary	Emergency supply storage, Remove VAT tiles in some classrooms.	\$ 16,000.00	DM	Project will need to be completed over summer when students and staff are not at the site.	Summer 2019
Indhurst High	Compliant labeling of electrical panels/mechanical panels.	\$ 2,500.00	RRMA	Hazard stickers included with District arc flash study. All other required labels are at an added cost.	In Progress
indhurst High	Lead paint remediation as needed (analysis needed).	\$ -	TBD	Walting on results from NAL.	In Progress
oma Rica Elementary	Compliant labeling of electrical panels/mechanical panels.	\$ 1,500.00	RRMA	Hazard stickers included with District arc flash study. All other required labels are at an added cost.	In Progress
oma Rica Elementary	Water testing and compliance (with remediation to be determined).	\$	Grant	Installed phosphorus system.	Testing is ongoing
Marysville High	Bleacher replacement.	\$ 87,000.00	TBD	Need clarification on this item. Waiting on response from site.	Pending
Marysville High	Compliant labeling of electrical panels/mechanical panels.	\$ 2,500.00	RRMA	Hazard stickers included with District arc flash study. All other required labels are at an added cost.	In Progress
Marysville High	Renovate boys' and girls' locker rooms.	\$ 130,000.00	TBD	Awalting approval on funding source.	Desired start Spring/Summer 2019
Marysville High	Replace east-facing gym doors.	\$ 30,000.00	RRMA	Getting estimates. We will schedule for Fall 2019.	Fall 2019
Marysville High	Roofing repair and replacement on older buildings.	\$ 460,000.00	DM	Roofing assessment completed summer 2018. We will make repairs as necessary.	Ongoing
Marysville High	Stucco and T-1-11 siding repair and replacement on various buildings,	\$ 42,000.00	DM	Have been replacing dry rot in areas. Work is ongoing.	
Marysville High	Tree removal on Kinney Lane.		RRMA	Getting estimates. Hazard stickers included with District arc	In Progress
McKenney Intermediate	Compliant labeling of electrical panels/mechanical panels.	\$ 1,500.00	RRMA	flash study. All other required labels are at an added cost.	Ongoing
McKenney Intermediate	Lead paint remediation as needed (analysis needed).	\$ 20,000.00	DM	W/O #5700. Contacted NAL for testing of various areas.	Ongoing
Olivehurst Elementary	Compliant labeling of electrical panels/mechanical panels.	\$ 1,500.00	RRMA	Hazard stickers included with District arc flash study. All other required labels are at an added cost, 50% complete.	Ongoing
Olivehurst Elementary	New Flooring remediation of VAT tiles in Multipurpose room.	\$ 70,000.00	DM	Getting estimates for remediation and replacement of the flooring.	Spring/Summer 2019
Olivehurst Elementary	Roofing on all older buildings/leaks.	\$ 11,000.00	RRMA	Ongoing repairs.	SKINAL SAMOUNT AND
Olivehurst Elementary	Water penetrationdry rot noted,	\$ 140,000.00	DM	Dry Rot repaired. Found HVAC flashing is leaking and needs replaced. Will replace flashing Spring/Summer 2019.	Ongoing
Yuba Feather Elementary	Compliant labeling of electrical panels/mechanical panels.	\$ 1,500.00	DM	Hazard stickers included with District arc flash study. All other required labels are at an added cost.	Ongoing
Yuba Feather Elementary	Gutters/downspouts/roof leaks (major dry rot on older classroom buildings).	\$ 45,000.00	DM	We have repaired areas of dry rot and will continue work as time allows. The site is scheduled for painting Summer 2019.	Spring/Summer 2019
Yuba Feather Elementary	Parking lot striping.	\$ 4,000.00	RRMA	W/O#5710	Spring/Summer 2019
Yuba Feather Elementary	Ventilation system upgrade/repair. Carbon monoxide, natural gas.	\$ 13,000.00	TBD	Need to meet with food services to understand the need.	Pending
Yuba Feather Elementary	Water testing and compliance (with remediation to be determined).	\$	RRMA	Installed phosphorus system. There will be quarterly testing throughout the year.	Ongoing
Yuba Gardens Intermediate	Compliant labeling of electrical panels/mechanical panels.	\$ 1,500.00	RRMA	Hazard stickers included with District arc flash study. All other required labels are at an added cost, 50% complete.	In Progress
Yuba Gardens Intermediate	Lead paint remediation as needed (analysis needed).	\$ 5,000.00	DM	W/O #5717. Working with NAL to determine location of said "lead paint".	Ongoing
Yuba Gardens Intermediate	Remove VAT tiles in permanent classrooms.	\$ 60,000.00	DM	W/O #5718 Working with abatement company for an estimate.	Summer 2019

		Non-FMP Tier 1	1 Proj	iects Buildin	as & Grounds		
5010G 548	Project	Readon for Project Priority			Funding Source		Status
Arboga Elementary	Intercom upgrade.	Safety	\$	39,420.00	TBD	Working with PBK Architect to obtain state School Facilities Program funding.	In Progress
Arboga Elementary	Siding	Deteriorating siding	\$	15,000.00	DM	pld and rotting	TBD
Browns Valley Elementary	Flooring.	Flooring is dated and beyond	\$	12,000,00	DM	Replace flooring multipurpose room.	Install scheduled for Winter 2018
Browns Valley Elementary	Fire pump.	Pump burned up	\$	26,000.00	RRMA	Working with contractor to rebuild the engine.	In Progress
Cedar Lane Elementary	Replace cafeteria tables		s	80,000.00	DM	old and needs replaced	TBD
		OCA Compiler	\$		TBD	Working with PBK Architect for closeout	In progress
Cedar Lane Elementary	Legacy.	DSA Compliance	,		180	recommendations.	all programs
Community Day	Lighting improvements.	Prop 39 funding via engineering report and EEP	\$	(4)	Prop 39	Replace 20 exterior light fixtures with LED. De-lamp and re-lamp T8 light fixtures to LED. Johnson Controls will complete work 2018/2019.	In progress
Cordua Elementary	Intercom upgrade.	Safety	\$	23,070.00	TDB	Estimate received. Tentatively scheduled for summer 2019	Scheduled for Summer 2019
Cordua Elementary	Build walls in teacher staff room.	Site request	\$	12,000.00	RRMA	Teachers need to be separate from students during their breaks.	Scheduled for Winter 2018
Cordua Elementary	Water testing & maintenance.	State requirement	\$	6,000,00	RRMA	Installed phosphorus system, Testing to continue quarterly.	Ongoing
Cordua Elementary	Roof repair	Roof failing	\$	120,000,00	DM	Estimate received, Tentatively scheduled for summer 2019.	Scheduled for Summer 2019
Covillaud Elementary	Shade structure in Kindergarten	Safety	5	50,000.00	General fund	No shade for children.	TBD
Covillaud Elementary	Access to the back of school	Safety	\$	11,000.00	DM	Grade area, concrete, and new gate	Scheduled Jan 2019
District Office	Roof repair Print shop	Leaks	\$	25,000.00	DM	Roof leaks	TBD
District Wide	HVAC unit replacements.	Safety	\$	400,000.00	DM	Ongoing 4 replaced - 3 remaining,	Ongoing
District Wide	Irrigation automation.	Energy conservation and operational efficiency	\$	500,000.00	DM	Add computerized controls at various gites. Ongoing.	Ongoing
Dobbins Elementary	Water treatment,	State and County requirement	\$	4,000.00	RRMA	Installed phosphorus system. Testing to continue quarterly.	Ongoing
File Florence	Cidles	Catanian siding		1E 000 00	DM		TBD
Ella Elementary	Siding	Deteriorating siding	\$	15,000,00		Needs to be replaced	
Ella Elementary	Painting of school		\$	40,000.00	DM	iDid and peeling	TBD
Ella Elementary	Legacy #1.	DSA Compliance	\$	37.6	TBD	Working with PBK Architect for closeout recommendations.	In Progress
Ella Elementary	Legacy #2.	DSA Compliance	\$	(4)	TBD	Fire Life Safety Scope - Working with PBK Architect for closeout recommendations.	In Progress
Ella Elementary	New electrical wiring needed in old classroom wings.	Potential fallure	\$	25,000.00	TBD	Buildings and Grounds are working on developing a scope of work for this project.	Investigating
Ella Elementary	Replace old clocks	To sync entire site	\$	32,000.00	DM	Waiting for estimate.	Pending
Ella Elementary	Tie-In old clocks	Routine maintenance	\$	3,600.00	RRMA	Maintenance has been working on replacement as time allows.	Ongoing
Ella Elementary	Plants, bark and trees need to be added as this has not been done	Site beautification	\$	2,600.00	RRMA	Replacing and adding plants and shrubs to various areas.	In progress
Edgewater Elementary	Add privacy slat to fence along	block site of park behind school	\$	6,400.00	General Fund		In progress
Edgewater Elementary	Add Title 5 kindergarten building	Needed due to growth	5	2,600,000.00	Fund 25	in design	In progress
Foothill Intermediate	Automatic Irrigation filter system.	Irrigation is getting clogged by sediment from BVID	\$	6,000.00	DM	Gathering parts list. Next step will be to schedule the install.	In Progress
Johnson Park Elementary	Landscaping.	Area floods and has tripping hazards	\$	6,000.00	TBD	Landscaping outside cafeteria area.	In Progress
Kynoch Elementary	Painting of school		5	40,000,00	DM .	Old and peeling	TBD
Linda Elementary Linda Elementary	Cafeteria table Siding	Replacing Deteriorating siding	5	70,000.00 15,000.00	DM DM	Beyond repair Siding deteriorating	TBD TBD
Linda Elementary	Legacy.	DSA Compliance	\$	350,000.00	TBD	Working with PBK Architect for closeout recommendations.	In Progress
Unda Elementary	Delamp and relamp.	Prop 39 Project	\$	1,600,00	Prop 39	Johnson Controls is working with MJUSD on Implementation. Completion date Spring 2019	In Progress
Lindhurst High	Landscape front of school	Site request	\$	13,000.00	RRMA	Received county approval to move forward with this project.	Spring 2019
Lindhurst High	Culinary Kitchen 11.	CTE grant; Improve program	\$	500,000.00	CTE/GF	Bid walk Dec 6th, Bid opening Jan 3rd, Jan 22nd approval of lowest bid	In progress
Marysville High	Ag-Mechanics	New program	\$	1,544,000.00	CTE/GF	Received lowest bid. Awaiting board approval	In Progress
Marysville High	South Auditorium	Modernization of existing space	5	295,305.00	GF	Lowest bid awarded. Construction starts	In Progress
Marysville High	Roof assessment.	Routine maintenance	\$		N/A	Nov. 14th. We will review report and make repairs	In Progress
Marysville High	Legacy	DSA Compliance	\$	(4)	TBD	as necessary, Working with PBK Architect for closeout recommendations	In progress
Marysville High	Lighting improvements.	Prop 39 funding via engineering Report and EEP	\$	4,200.00	Prop 39	Johnson Controls is working with MJUSD on implementation of prop 39 projects. Completion date Spring 2019.	In progress
Marysville High	Tree removal	Many trees are dead and need removed	\$	3,600.00	DM	Tree removal on Kinney Lane.	In Progress
MCAA	New Classroom	space needed for programs	\$	200,000.00	MCAA	Building delivery date set for Oct	In prograss
McKenney Intermediate	New Cafeteria tables		5	80,000.00	General Fund	Old and needs replaced	TBD
McKenney Intermediate	Various Prop 39 Improvements.	Energy efficiency measures	\$	t	Prop 39	Johnson Controls will complete work 2018/2019.	In progress
Olivehurst Elementary	Legacy.	DSA Compliance	\$	2)	TDB	Working with PBK Architect for closeout recommendations.	In Progress
Olivehurst Elementary	Various Prop 39 Improvements.	Prop 39 funding via engineering report and EEP	\$	*	Prop 39	Johnson Controls will complete work 2018/2019.	In Progress
Yuba Feather Elementary	Painting of school	and the same of th	\$	40,000.00	DM	Old and peeling	TBD
Yuha Feather Elementary	Repairing roof	Deteriorating roof	\$	150,000.00	DM	Estimate received. Tentatively scheduled for summer 2019.	TBD
Yuba Feather Elementary	Legacy.	DSA Compliance	\$	*	TBD	Working with PBK Architect for closeout recommendations.	In Progress
Yuba Gardens Intermediate	Intercom upgrade.	Safety	\$	72,741.00	TBD	Estimate received. Potentially scheduled	Pending
ACCORDING NO. OF A STATE OF	The state of the second	Prop 39 funding via engineering	\$		Prop 39	for summer 2019. Johnson Controls will complete work	In Progress
Yuba Gardens Intermediate	Various Prop 39 Improvements.	report and EEP	1 *	1.53	Prop 39	2018/2019	In Progress

	FMP Tier 1 Proje	cts	Buildings	& Grounds	Completed	
			Estimated	Funding		
School Site Arboga Elementary	Project Asbestos report (AHERA) due/remediation as needed.	5	700.00	Source RRMA	Notes Work order #3731	Status Completed
Arboga Elementary	Replace asphalt playground.	5	80,000.00		2017	Completed
Browns Valley Elementary	Compliant labeling of electrical panels/mechanical panels.	\$	1,500,00	RRMA	Hazard stickers included with District arc flash study. All other required labels are at an added cost. Maintenance has completed.	Completed
Browns Valley Elementary	Asbestos report (AHERA) due.	\$	700,00	RRMA	2017	Completed
Browns Valley Elementary Browns Valley Elementary	Lead paint remediation as needed (analysis needed). Modernize/replace exit/entrance interior signage	5	800.00	RRMA	Work order #5662 Work order #3724	Completed Completed
Cedar Lane Elementary	Stucco and T1-11 siding repair and replacement on various older buildings.	\$	8,000.00		Word order #5649 Cost dependent upon District ADA study, Site	Completed
Cedar Lane Elementary	ADA drinking fountains.	\$	*		visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Complete
Cordua Elementary	Asbestos report (AHERA) due.	5	700,00		Work order #3731 Hazard stickers included with District arc flash	Completed
Covillaud Elementary	Compliant labeling of electrical panels/mechanical panels.	\$	1,500.00	RRMA	study. All other required labels are at an added cost.	Completed
Covillaud Elementary	Ashestos report update.	\$	700.00	RRMA	Work order #3731	Completed
Ella Elementary	Replanting of missing and dead trees and shrubs.	5	5,500.00	RRMA	Getting estimates. All Identified roofing issues have been	Completed
Ella Elementary	Roofing on all older buildings/leaks. Exterior painting/stucco.	\$	30,000.00	DM	addressed. Via roofing repairs of outside contractor	Completed Completed
Ella Elementary	Seal gaps and plumbing openings.	\$	500.00	RRMA	Work order #3722	Completed
Ella Elementary Foothill Intermediate	Soffits	\$	1,500.00	RRMA	mazaro stickers included with district are hash	Completed
Foothill Intermediate	Compliant labeling of electrical panels/mechanical panels. Roofing - major leaks and past leaks (throughout).	8	50,000.00	KKMA	Work order #5677	Completed
Foothill Intermediate	Seal gaps and plumbing openings,	\$	500.00	RRMA	Work order #3723	Completed
Foothill Intermediate	Soffits Storm drain improvements to relieve clogging, unsafe ditch	\$	2 222 22		W. L. 4. 45670	Completed
Foothill Intermediate	areas and undersized system	\$	8,000,00		Work order #5678	Completed
Foothill Intermediate	Waste water system Improvements.	\$	45,275.00	Bond	Main project completed in 2015. Re-do hardscape in and around new waste water pipe by Fall 2017 - Includes new asphalt seal, additional fencing, signs, and landscaping. Contract for new asphalt seal approved by the Board on 10/25/16. Work to be scheduled after shade canopy completed.	Completed
Foothill Intermediate	Water penetration.	\$	60,000.00		Work order #5924 mazaru suckers included with district are flash	Completed
Johnson Park Elementary	Compliant labeling of electrical panels/mechanical panels.	\$	1,500,00 5,000,00	RRMA RRMA	ship the street and labels are it as	Completed Completed
Johnson Park Elementary Johnson Park Elementary	Repair dry rot - near multipurpose Room. Asbestos report (AHERA) due.	\$	700.00	RRMA	Work order #3731	Completed
Johnson Park Elementary	Roofing (leaking noted in main building).	8	45,000.00		Scope is just to install a door buzzer. Adding	Completed
Johnson Park Elementary	Visitor entry Controlled access	\$	1,500.00		a camera would be additional.	Completed
Kynoch Elementary	Flashing problems	5	45,000.00 700.00	RRMA RRMA	W/O #5927 Work Order #3731	Completed Completed
Kynoch Elementary Kynoch Elementary	Asbestos report (AHERA) due. Lead paint remediation as needed (analysis needed).	\$	20,000.00	KKMA	Work order #3731 Work order #5681	Completed
Kynoch Elementary	Modernize/replace exit/entrance interior signage.	\$	900,00 75,000.00	RRMA	Work order #3729	Completed Completed
Kynoch Elementary Kynoch Elementary	Repair dry rot, especially near windows. Water penetration near old windows.	5	71,000.00		Kiz Construction Kiz Construction	Completed
Lindhurst High	Asbestos report (AHERA) due.	1	850.00	RRMA	Work order #3731	Completed
Lindhurst High Lindhurst High	Drinking fountains. Football field renovation.	5	8,000.00 128,000.00	DM	Completed. Safety	Completed Completed
Loma Rica Elementary	Foundation damage from water flows under portable buildings: water flows under portable classroom foundations (2 older	\$	200.00	RRMA	Maintenance made repairs and has checked foundation. No damage to foundation.	IC25WAY5
Loma Rica Elementary	portables) to prevent foundation damage and smells. Asbestos report (AHERA) due.	\$	700.00	RRMA	Wark order #3731	Completed Completed
Loma Rica Elementary	Carpets in 3 older portables (If not replaced with new modular	5	14,300.00	- JOHNIO	Work order #5687	
Loma Rica Elementary	classroom). Clean out existing storage at "well building" to provide safety distances. Striping needed from electrical and mechanical	\$	8		Completed.	Completed
Loma Rica Elementary	panels. Verify overhang supports at permanent classroom building.	\$		1	Work order #5693	Completed Completed
Marysyllle Community Day	Install security camera system.	\$			Completed,	Completed
Marysville High	Gutters/downspouts.	\$	5,000.00	RRMA	Maintenance made repairs and cleaned outters.	Completed
Marysville High	HVAC upgrades campus wide.	\$	b	Prop 39 & others TBD	Cost based on what we can do under Prop 39 only, 15 5-ton and 5 3-ton can be completed via Prop 39. Direct purchase of 5 3-ton units is \$15,460 plus disconnects, Labor to install owner purchased BARD units is \$4,675. Economizers are \$1,800 each and thermostats \$750 each. Price to install 5-ton unit is roughly \$8,150. Two 7.5 library units need to be replaced as well as 4 ton units and controls.	Completed
McKenney Intermediate	Roofing room 16 and P4 reported roof leaks. Roofing report forthcoming.	\$	25,000.00	RRMA	Replaced HVAC unit which was causing the roof to leak.	Completed
McKenney Intermediate	Ashestos report (AHERA) due.	\$	700.00	RRMA	Work Order #3731	Completed
Olivehurst Elementary	Seal gaps and plumbing openings.	\$		RRMA	Plumbers went around and sealed gaps.	Completed
Yuba Feather Elementary	Demolish floor tile of older restroom building (if not replaced). Exterior door and hardware of older restroom building (if not	\$	4,500.00		Work order #5942	Completed
Yuba Feather Elementary	replaced).	\$	6,000.00		Work order #5706	Completed
Yuba Feather Elementary	Exterior lighting of older restroom building (if not replaced).	\$	1,300.00		Work order #5707	Completed
Yuba Feather Elementary	Exterior painting of older restroom building (if not replaced).	\$	4,600.00		Work order #5708	Completed
Yuba Feather Elementary	Floor tile of older restroom building (if not replaced).	\$	4,500.00		Work order #5942	Completed
Yuba Feather Elementary	Gas stove replacement.	\$	2,000.00			Completed
Yuba Feather Elementary Yuba Feather Elementary	Interior painting of older restroom building (if not replaced). Kitchen ventilation issues; carbon monoxide detector has been	\$	1,200.00	RRMA	Work Order #5936 Work Order #3727	Completed
Yuba Feather Elementary	disabled. Gas smells at times also. Parking lot signage.	5	600.00	RRMA	Work Order #3728	Completed Completed
Yuba Feather Elementary	Replace wainscot of older restroom building (If not replaced)	\$	1,600.00	- J.J. K.	Work order #5712	
	Roofing (major leaks and past leaks throughout) on existing	+-				Completed
Yuba Feather Elementary	older classroom wings.	\$	70,000.00	00000	Work order #5713	Completed
Yuba Feather Elementary Yuba Feather Elementary	Seal gaps and plumbing openings . Wall tile of older restroom building (If not replaced).	5	12,000.00	RRMA	Work Order #3730 Work order #5714	Completed Completed
Yuba Feather Elementary Yuba Feather Elementary	Large field automation irrigation project.	\$	26,000.00			Completed
Yuba Gardens Intermediate	Asbestos report (AHERA) due	\$		RRMA	Work order #3731	Completed
Yuba Gardens Intermediate	Cafeteria table replacement	\$	19,258.00	General Fund Business Services		Completed
Yuba Gardens Intermediate	Roofing (leaking noted in main building).	\$	13,000.00		Work order #5719	Completed

Actions the mininger Actions (Permissive)			Non-FMP Tier 1 Proje	cts Bi	uildings & (Graunds Com	pleted	
Access Emeritary (School Site	Project	Reason for Project Priority		mated Cost	Funding Source	Notes	Status:
Antennet Profession Company						General Fund -		
Marchy Demonstray General Exclusion Service Serv	Arboga Elementary		Safety	\$	43,000.00	One-Time		Completed
ACCOUNT ACCO	Arboga Elementary	Removal Eucalyptus tree	Safety	5	800.00	- Marketonial X		Completed
About 1	Arboga Elementary	General repairs	Site request					
Part	***************************************			-				
Anthon Commontary Commont				_			sidewalk.	
Community Description De							Installed area drain and base rock.	Completed
Second Special Description Process Proce			Safety	\$	2.600.00	RRMA	Replaced septic pump. Added fencing in back of school.	
	Browns Valley Elementary	Flooring.	Beyond repair	\$	6,000.00			Completed
Color Lame District And Provided 1945								
Content team feature of the content of the conten		1	NAME OF THE PARTY				Installed new drinking fountain on	
Column C			Broken and can not be repaired	\$	3,000.00		blackton,	
		Removed and replaced all outside				RAPIA	Cower Wildows III D. Wild.	***
Collect arm Elementary Gallary desposed Secular	Cedar Lane Elementary		Safety	\$	6,100.00			Completed
Control Cont	Cedar Lane Elementary		Routine maintenance	5	300.00			Completed
Community Days Restrict, Protecting is detected and is beyond regalf receiption of regalf and in beyond regalf receiption of the regalf protection of \$ 4,000.00 Per Regalf Restrict primaris office. Protection of the regalf protection of the regal	Cedar Lane Elementary	Garbage disposal.	Routine maintenance	\$	300.00			Completed
Community Day Septic pump. Needs to be registed \$ 1,000.00 Right Right Register story; Completed Community Day Septic pump. Reeds to be registed \$ 1,400.00 Content Pump of Completed Pump of	Cedar Lane Elementary	Concrete grinding 300'	Routine maintenance	\$	1,600.00			Completed
Coviliand Elementary Trim and thin 2 Mulberry trees Safety \$ 1,400.00 Ceneral Fund Installed new drinking fourtain at properties of the work. Coviliand Elementary Tree work. Coviliand Elementary Repaired by Safety \$ 2,600.00 DM Appliat was beyond repair to preschool. Coviliand Elementary Repaired by WAG unit replacement. Units or main building are old a 20,000.00 DM Appliat was beyond repair to preschool. Coviliand Elementary Repaired by WAG unit replacement. Units or main building are old a 20,000.00 DM Rev HVAC unit installed - main building are old a 20,000.00 DM Rev HVAC unit installed - main building are old a 20,000.00 DM Rev HVAC unit installed - main building are old a 20,000.00 DM Rev HVAC unit installed - main building are old a 20,000.00 DM Rev HVAC unit installed - multipurpose completed common. Coviliand Elementary Profiting. Coviliand Elementary Reproduction Repair Repai	Community Day	Flooring		\$	8,000.00	DM	Replaced flooring in main office.	Completed
Covillated Elementary Particular Properties of People Peop	Community Day	Septic pump.	Needs to be replaced	\$	4,500.00	RRMA	Replaced septic pump.	Completed
Covillaud Elementary Fountain. Beyond repair \$ 00.000	Covillaud Elementary	Trim and thin 2 Mulberry trees	Safety	\$	1,400.00	General Fund		Completed
Coviliaud Elementary Regrade ball wall area. Safety \$ 16,000.00 DM Apphalt was beyond repair so replacement, was necessary. Completed and beyond repair so a	Covillaud Elementary	Fountain	Beyond repair	\$	800,00	DM		Completed
Covillaud Elementary Regrade bell wall area. Selety 9 1 15,000.00 DM replacement was necessary. Confided Elementary HVAC unit replacement. Units on main building are old and beyond repair of an and building are old and beyond repair of an and building are old and beyond repair of an and building are old and beyond repair of an and building are old and beyond repair of an and building are old and beyond repair of an and building are old and beyond repair of an and building are old and beyond repair of an and building are old and beyond repair of an and building are old and beyond repair of an and building are old and beyond repair. Covillaud Elementary Planting. Beyond repair of the asphalts the analysis of the asphalts and replaced within rew. Cordua Elementary Principal Confidence Safety Sa	Covillaud Elementary	Tree work.		\$	2,600.00	RRMA		Completed
Covillaud Elementary PARC unit replacement. Units on main building are old and beyond repair of depair of	Covillaud Elementary	Regrade ball wall area	Safety	\$	16,000.00	DM		Completed
Covillaud Elementary Painting: and beyond repair spatient in several years pathed in several years pat	Covillaud Elementary	HVAC unit replacement.		\$	20,000.00	DM	New HVAC unit installed - main building,	Completed
Covillaud Elementary Paintong. painted in several years painted years painted in several years painted in several years painted years	Covillaud Elementary	HVAC unit replacement.		\$	6,000.00	DM		Completed
Covillaud Elementary Playground repair. needs replaced 9 1, 10,000,00 DM new. completed Covillaud Elementary Rooring. Beyond repair \$ 3,200,00 DM Rooring replaced - office. Completed Covillaud Elementary Frim canopy/thin trees Safety \$ 15,000,00 General fund Completed Completed Cordua Elementary Trim and thin Elm trees Safety \$ 2,700,00 General Fund Completed Cordua Elementary RVAC unit replacement Beyond repair \$ 5,000,00 DM Rew HVAC unit installed - rooms 1 & 2. Completed Cordua Elementary RVAC unit replacement Beyond repair \$ 5,000,00 DM Rew HVAC unit installed - Principal's Completed Cordua Elementary RVAC unit replacement Beyond repair \$ 5,000,00 DM Rew HVAC unit installed - Principal's Completed Cordua Elementary RVAC unit replacement Beyond repair \$ 5,000,00 DM Rew HVAC unit installed - Principal's Completed Cordua Elementary RVAC unit replacement Beyond repair \$ 1,500,00 DM Rew HVAC unit installed - Principal's Completed Cordua Elementary RVAC unit replacement Beyond repair \$ 1,500,00 DM Rew HVAC unit installed - Principal's Completed Cordua Elementary RVAC unit replacement Beyond repair \$ 1,500,00 DM Rew HVAC unit installed - Principal's Completed Cordua Elementary RVAC unit replacement Beyond repair \$ 1,500,00 DM Rew HVAC unit installed - Principal's Completed Cordual Elementary RVAC unit replacement Beyond repair \$ 1,500,00 DM Rew HVAC unit installed - Principal's Completed Remember Principal Remember	Covillaud Elementary	Painting.		\$	11,000.00	DM	Painted exterior trim.	Completed
Coviliaud Elementary Flooring. Beyond repair \$ 3,600.00 DM Flooring replaced - classrooms. Completed Cordua Elementary Trim canopy/thin trees Safety \$ 1,5,000.00 General Fund Cordua Elementary Trim and thin Elm trees Safety \$ 2,700.00 General Fund Cordua Elementary HVAC unit replacement Beyond repair \$ 5,000.00 DM New HVAC unit installed-rooms 1 & 2. Completed Cordua Elementary HVAC unit replacement Beyond repair \$ 5,000.00 DM New HVAC unit installed-rooms 1 & 2. Completed Cordua Elementary HVAC unit replacement Beyond repair \$ 5,000.00 DM New HVAC unit installed-rooms 1 & 2. Completed Cordua Elementary Tree work Safety \$ 1,500.00 DM New HVAC unit installed-rooms 1 & 2. Completed Cordua Elementary Paning. Safety \$ 1,500.00 RRMA Find Cordua Elementary Paning. Store requested. \$ 3,600.00 RRMA Painted north wind and east wind. Completed Corduilation Shoreline power. Siter requested. \$ 3,600.00 RRMA Painted north wind and east wind. Completed Corduilation Cordua Elementary Shoreline power. Safety. \$ 1,200.00 RRMA Painted north wind and east wind. Completed Completed Corduilation Corduilation Corduilation Shoreline power. Safety. \$ 1,200.00 RRMA Painted north wind and east wind. Completed Corduilation Corduilatio	Covillaud Elementary	Playground repair.		\$	16,000.00	DM		Completed
Cordua Elementary Trim canopy/thin trees Safety \$ 15,000.00 General fund Completed Cordua Elementary Trim and thin Elin trees Safety \$ 2,700.00 General Fund Completed Cordua Elementary HVAC unit replacement Beyond repair \$ 5,000.00 DM New HVAC unit installed - Principal's Completed Cordua Elementary HVAC unit replacement Beyond repair \$ 5,000.00 DM New HVAC unit installed - Principal's Completed Cordua Elementary Tree work Safety \$ 1,500.00 RRMA Tree canopy needs lightened as the added welph can cause branches to fall Completed Cordua Elementary Painting, Beutification Remover. Site requested. \$ 3,600.00 DM Painting, Completed Covillaud Shoreline power. Safety. \$ 1,200.00 PM Painting, Completed Covillaud Connect walk in freezer. Safety. \$ 1,200.00 PM Painting, Completed District Office Removal of 4 trees by train treestle steel by train treestle power. Safety \$ 1,200.00 PM Painting, Completed Painting, Co	Covillaud Elementary	Flooring.	Beyond repair	\$	3,200.00	DM	Flooring replaced - office.	Completed
Cordua Elementary Trim and thin Elm trees Safety \$ 2,700.00 DM New HVAC unit installed -rooms 1 & 2. Completed Cordua Elementary HVAC unit replacement Beyond repair \$ 5,000.00 DM New HVAC unit installed -rooms 1 & 2. Completed Cordua Elementary Tree work Safety \$ 1,500.00 RRMA Tree canopy needs lightened as the added weight can cause branches to fall completed Cordua Elementary Painting. Beutification Ster requested. \$ 3,600.00 RRMA Painted north wing and east wing. Completed C	Covillaud Elementary	Flooring	Beyond repair	\$	3,600.00	DM	Flooring replaced - classrooms,	Completed
Cordua Elementary HVAC unit replacement Beyond repair Service Safety Service Safe	Cordua Elementary	Trim canopy/thin trees	Safety	\$	15,000.00	General fund		Completed
Cordua Elementary HVAC unit replacement Beyond repair \$5,000.00 DM New HVAC unit installed - Principal's Completed Office. Cordua Elementary Tree work Safety \$1,500.00 RRMA Tree canopy needs lightened as the added weight can cause branches to fall. Completed Cordulate Elementary: Painting Beutification RRMA Painted north wing and east wing. Completed Cordulated Shoreline power. Site requested. \$3,500.00 RRMA Painted north wing and east wing. Completed Complete	Cordua Elementary	Trim and thin Elm trees	Safety	\$	2,700.00	General Fund		Completed
Cordua Elementary Tree work Safety \$1,500.00 RRMA Tree canopy needs lightened as the added weight can cause branches to fall completed Cordua Elementary Painting, Shoreline power. Site requested. Safety. Safety. \$1,200.00 RRMA Painted north wing and east wing. Completed Compl	Cordua Elementary	HVAC unit replacement	Beyond repair	\$	5,000.00	DM	New HVAC unit installed-rooms 1 & 2.	Completed
Cordua Elementary Free work Safety Sa	Cordua Elementary	HVAC unit replacement	Beyond repair	\$	5,000.00	DM		Completed
Covillaud Shoreline power. Site requested. \$ 3,600,00 Completed Covillaud Connect walk in freezer. Safety. \$ 1,200.00 Completed District Office Removal of 4 trees by train trestle District Office Ran conduit new lighting parking lot/Transportation. District Office Spray/injection program. Damage caused by tree droppings District Office Repave behind Transportation and Grounds. District Office Remodel. District Office Remodel. District Office Remodel. Contacted Garland Roofing as repairs were too large for Maintenance served of the Summer and Pagil. Completed	Cordua Elementary	Tree work	Safety	\$	1,500.00		added weight can cause branches to fall.	
Coviliaud Connect walk in freezer. Safety. \$ 1,200.00 \$ 1,200.00 Completed Complet				\$	3,600.00	RRMA	Painted north wing and east wing.	
bistrict Office Ran conduit new lighting parking District Office Ran conduit new lighting parking District Office Rapave behind Transportation and Grounds. District Office Remodel. Contacted Garland Roofing as repairs were too large for Maintenance Roofing. Roofing. Safety \$ 1,200.00 RRMA We have treated for the Summer and Fall. Remodeled office/Transportation Remodeled office/Transportation Department. Completed			SAN PRODUCTION OF THE PROPERTY					
District Office Remodel. District Office Renofing. District Office Renofing. Conpleted Gariand Roofing as repairs were too large for Maintenance Roofing.	District Office		Safety	\$	5,500.00		1	Completed
District Wide Spray/Injection program. Damage caused by tree drooplings \$ 10,000.00 RRMA We have treated for the Summer and Fall. Completed Spray/Injection program. Area is beyond repair and needs and Grounds. Page behind Transportation and Groun	District Office		Safety	\$	1,200.00			Completed
District Office Remodel. Completed SprayInjection program. Area is beyond repair and needs and Grounds. Remodel SprayInjection program. Area is beyond repair and needs and Grounds. Remodel Spray Rem		A CONTRACTOR OF THE PROPERTY O				DDMA	We have treated for the Summer and	
District Office and Grounds. replaced \$120,000.00 DM Remodeled office/Transportation Completed District Office Remodel. Contacted Garland Roofing as repairs were too large for Maintenance \$2,500.00 DM Roof has been repaired. Completed	100		droppinas				Fall.	
District Office Remodel. Contacted Gariand Roofing as repairs were too large for Maintenance \$ 2,500.00 DM Roof has been repaired. Completed	W.	and Grounds.		\$	120,000.00	DM	C	
District Office Roofing. repairs were too large for Maintenance \$ 2,500.00 DM Roof has been repaired. Completed	District Office	Remodel.	Control of Control of Control					Completed
	District Office	Roofing.	repairs were too large for	\$	2,500.00	DM	Roof has been repaired.	Completed
District Office General repairs. Site request \$ 300.00 RRMA Tack board installed at Student Services. District Office General repairs. Site request \$ 500.00 RRMA Patch work and paint Campleted				_			Services.	

			_				
District Office	Sewer repair	Sewer backs up dally. Line	ś	1,500.00	RRMA	Replaced old sewer line with updated system to help with drainage -	Completed
District Office	Jewel Tepuli	collapsed				Transportation Department. Installed new car lift/Transportation	
District Office	Truck/Car Lift.	Site request	\$	400.00	RRMA	Department.	Completed
District Office	Remodel.	Site Request	\$	1,800.00	RRMA	Frame and remodel Get Ready Room/Transportation Department	Completed
District Office	Remodel,	Site Requested	\$	350.00	RRMA	Remodeled maintenance office -	Completed
District Office	General repairs.	Safety	\$	800.00	RRMA	installed tack board Replaced concrete at bus wash after leak was repaired/Transportation	Completed
District Office	Remodel.	Safety	\$	3,500.00	RRMA	Department. Remodeled breakroom/District Office due to roof leak	Completed
District Office	Remodel	Site request	\$	1,500,00	RRMA	Remodeled conference room and front	Completed
District Office	Exterior repairs.	Safety	5	900.00	RRMA	office/Maintenance Building. Sewer pipe by wash rack.	Completed
District Office	Roofing.	safety	\$	1,300.00	RRMA	Roof repair at print shop.	Completed
District Office	Window replacement.	Routing maintenance.	5	43,000.00 3,630.00			Completed Completed
District Office	HVAC replacement.	Routine maintenance.	-				
District Office	Add outside light.	Safety.	\$	300.00			Completed
District Office	Roof leak above shredder.	Routine maintenance.	. 5	500.00			Completed
District Office	Replace water heater - Girls restroom.	Routine maintenance.	\$	1,500.00			Completed
District Office	Lead paint abatement.	Safety.	\$	40,000.00			Completed
District Office	Repaye back road,	Potential damage to District	\$	145,000.00			Completed
District Office	Renovate break room.	vehicles/Safety issue. Safety/remediation.	\$	6,000.00	RRMA	Completion Nov 2017.	Completed
District Office	Tree pruning.	Safety.	5	4,500.00	RRMA		Completed
District Office	Auditorium partial roof replacement	Safety	\$	42,000.00	RRMA	Replaced sections of roofing and broken tiles.	Completed
District Wide	Site Evacuation Maps	Base Map with path of travel and evacuation areas depicted.	\$	50,000.00	General Fund	Each site map has been sent to each school.	Completed
Dobbins Elementary	Exterior repairs.	Safety	\$	1,600.00	DM	Rock drainage ditch:	Completed
Dobbins Elementary	Fencing	Safety	\$	60.00	RRMA	Removed temporary fencing.	Completed
				400,00	RRMA		Completed
Edgewater Elementary	Dishwasher.	Food service request for support	\$			Repaired dishwasher,	
Edgewater Elementary Edgewater Elementary	Bark shrub beds. Remove fixtures.	Safety and site beautification Routine maintenance.	\$	1,000.00	RRMA	Added bark to necessary areas.	Completed
			\$	348,200.00		In progress Estimated completion Dec	Completed
Edgewater Elementary	Restroom building replacement.	Safety.	,	4,765.00		2017.	Completed
Ella Elementary Ella Elementary	Plant shrubs/landscaping General repairs	Site beautification Safety	1	3,200.00	DM	Stucco wall and paint.	Completed
Ella Elementary	Painting.	Safety	\$	900.00	RRMA	Non-skid (all portable ramps).	Completed
Ella Elementary	Flooring.	Flooring is beyond repair	\$	3,300.00	DM	Replaced flooring - room B102.	Completed
Ella Elementary	Roofing.	Roof needs repairs as it is leaking	\$	2,400.00	DM	Repaired roof - main building.	Completed
Ella Elementary	Ice maker/copy room.	Site request	ş	6,000.00			Site Canceled project
Ella Elementary	A/C line clean.	Routine maintenance.	\$	300.00			Completed Completed
Ella Elementary	Replace cafeteria HVAC unit.	System failure.	5	31,500,00 600,00	DD144	Description to the Lock on conner	Completed
Foothill Intermediate	Boller tank.	The tank is old and needs repairs	\$	400.00	RRMA	Repaired boller tank - leak on copper.	
			- 5				
Footbill Intermediate	Painting,	site request Safety	5		RRMA	Painted blackboards and murals	Completed Completed
Foothill Intermediate Foothill Intermediate Foothill Intermediate	Painting, Fencing, New cafeteria tables,	Safety, Safety,	\$	3,700.00	RECPIA	Painted blackboards and murals.	Completed Completed Completed
Foothill Intermediate Foothill Intermediate Foothill Intermediate	Fencing New cafeteria tables Pull up bars	Safety. Safety. Routine maintenance.	\$	3,700.00 28,000.00 1,600.00	кила	Painted blackboards and murals	Completed Completed Completed
Foothill Intermediate Foothill Intermediate Foothill Intermediate Foothill Intermediate	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1	Safety. Safety. Routine maintenance. Safety.	5	3,700.00 28,000.00 1,600.00 8,100.00	RRPIA	Painted blackboards and murals.	Completed Completed Completed Completed
Foothill Intermediate Foothill Intermediate Foothill Intermediate Foothill Intermediate Foothill Intermediate	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2	Safety. Safety. Routine maintenance. Safety. Safety.	\$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00	кела	Painted blackboards and murals.	Completed Completed Completed Completed Completed
Foothill Intermediate	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops	Safety. Safety. Routine maintenance. Safety. Safety. Safety.	\$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 700.00	К КРИД	Painted blackboards and murals.	Completed Completed Completed Completed Completed Completed Completed Completed
Foothill Intermediate	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops RUP rap	Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety.	\$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 700.00 8,000.00		Painted blackboards and murals.	Completed Completed Completed Completed Completed Completed Completed Completed
Foothill Intermediate	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops RUP cap Landscape playfield	Safety. Safety. Routine maintenance. Safety. Safety. Safety. Safety. Afready planned.	\$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 700.00	RRMA	Painted blackboards and murals.	Completed Completed Completed Completed Completed Completed Completed Completed
Foothill Intermediate	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure.	Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety.	\$ \$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 700.00 8,000.00 60,000.00		Painted blackboards and murals.	Completed
Foothill Intermediate	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops RIP rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of	Safety. Already planned. Safety.	\$ \$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 700.00 8,000.00 60,000.00 8,651.00		Painted blackboards and murals.	Completed
Foothill Intermediate	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school	Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Lack of shade.	\$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 700.00 8,000.00 65,000.00 100,000.00 45,000.00	RRMA RRMA	Repaired roof - main building,	Completed
Foothill Intermediate	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase I Keystone block wall/phase S Basketball hoops Bup rap Landscape playfield. Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring.	Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Lack of shade. No automation. Roof jeaks	\$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 700.00 8,000.00 60,000.00 100,000.00 45,000.00 3,320.00 16,000.00	RRMA RRMA DM DM	Repaired roof - main building, Flooring replaced - restrooms,	Completed
Foothill Intermediate	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school	Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Lack of shade. No automation.	\$ \$ \$ \$ \$ \$ \$	3,700,00 28,000,00 1,600,00 8,100,00 4,000,00 50,000,00 8,651,00 100,000,00 45,000,00 45,000,00 16,000,00 40,000,00	RRMA RRMA DM DM DM	Repaired roof - main building, Flooring replaced - restrooms, Remodeled staff and boys/girls restrooms,	Completed
Foothill Intermediate Johnson Park Elementary	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rup rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom repairs	Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 8,100.00 6,000.00 8,000.00 60,000.00 100,000.00 45,000.00 45,000.00 10,000.00 1,500.00	RRMA RRMA DM DM DM DM RRMA	Repaired roof - main building, Flooring replaced - restrooms, Remodeled staff and boys/girls restrooms. Fixed all walls in restrooms.	Completed
Foothill Intermediate Johnson Park Elementary	Fencing. New cafeteria tables. New cafeteria tables. Pull up bars. Keystone block wall/phase 2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing. Flooring. Restroom remodel. Restroom repairs Painting	Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Already planned. Safety. Already planned. Safety. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 8,000.00 60,000.00 8,651.00 100,000.00 45,000.00 45,000.00 40,000.00 1,500.00	RRMA RRMA DM DM DM DM DM	Repaired roof - main building, Flooring replaced - restrooms, Remodeled staff and boys/girls restrooms,	Completed
Foothill Intermediate Johnson Park Elementary	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops RUP rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom remodel, Restroom repairs Painting Painting Painting Painting Painting	Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Already planned. Safety. Already planned. Safety. No automation. Roof leaks Restrooms are old smelly and outdated. Safety maintenance Routine maintenance	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 700.00 8,000.00 8,651.00 100,000.00 45,000.00 3,320.00 16,000.00 1,500.00 11,000.00 120.00	RRMA RRMA DM DM DM DM RRMA DM RRMA	Repaired roof - main building, Flooring replaced - restrooms, Remodeled staff and boys/girls restrooms, Fixed all walls in restrooms. Painted front Administrative building.	Completed
Foothill Intermediate Johnson Park Elementary	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield. Repave blacktop area Shade structure. Automation of field and front of school Roofing. Filooring. Restroom remodel. Restroom repairs Fainting Painting Painting Replace 2 sets of double doors on main building.	Safety. Already planned. Safety. No automation. Roof jeaks Restrooms are old smelly and outdated. Safety. Routine maintenance Routine maintenance Safety.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 8,100.00 4,000.00 8,000.00 60,000.00 45,000.00 45,000.00 45,000.00 16,000.00 1,500.00 120.00 22,000.00	RRMA RRMA DM DM DM RRMA DM RRMA RRMA RRMA	Repaired roof - main building, Flooring replaced - restrooms, Remodeled staff and boys/girls restrooms, Fixed all walls in restrooms. Painted front Administrative building.	Completed
Foothill Intermediate Johnson Park Elementary	Fencing. New cafeteria tables. New cafeteria tables. Pull up bars. Keystone block wall/phase2 Basketball hoops Rup rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing. Flooring. Restroom remodel. Restroom repairs Painting Painting Painting Painting Painting Painting	Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Already planned. Safety. Already planned. Safety. No automation. Roof leaks Restrooms are old smelly and outdated. Safety maintenance Routine maintenance	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 700.00 8,000.00 8,651.00 100,000.00 45,000.00 3,320.00 16,000.00 1,500.00 11,000.00 120.00	RRMA RRMA DM DM DM DM RRMA DM RRMA	Repaired roof - main building, Flooring replaced - restrooms, Remodeled staff and boys/girls restrooms, Fixed all walls in restrooms. Painted front Administrative building.	Completed
Foothill Intermediate Johnson Park Elementary	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase 1 Keystone block wall/phase 2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom repairs Painting Painting Replace 2 sets of double doors on main building. Cut down and remove dead tree	Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Already planned. Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Routine maintenance Safety.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 8,100.00 4,000.00 8,000.00 8,651.00 100,000.00 45,000.00 45,000.00 1,500.00 1,500.00 120.00 22,000.00 42,670.00	RRMA RRMA DM DM DM RRMA DM RRMA RRMA RRMA	Repaired roof - main building, Flooring replaced - restrooms, Remodeled staff and boys/girls restrooms, Fixed all walls in restrooms. Painted front Administrative building.	Completed
Foothill Intermediate Johnson Park Elementary	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase 2 Basketball hoops Rup rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom remodel, Restroom repairs Fainting Painting Painting Landscape field near new building. Landscape field near new	Safety. Safety. Routine maintenance. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Routine maintenance Safety. Already planned. Safety. Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 8,100.00 8,000.00 60,000.00 8,651.00 100,000.00 45,000.00 15,000.00 1,500.00 120.00 22,000.00 1,000.00	RRMA DM DM DM DM RRMA DM RRMA DM RRMA DM RRMA	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter	Completed
Foothill Intermediate Johnson Park Elementary	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom repairs Painting Painting Replace 2 sets of double doors on main building. Landscape field near new building. Cut down and remove dead tree Flooring.	Safety. Routine maintenance. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Routine maintenance Safety. Already planned. Safety. Flooring is old and beyond repair Cal Water mandated we add this	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 60,000.00 8,651.00 100,000.00 45,000.00 45,000.00 16,000.00 1,500.00 120.00 22,000.00 42,670.00 1,000.00 4,800.00	RRMA DM DM DM RRMA DM RRMA DM RRMA DM RRMA DM RRMA ROM RRMA DM DM RRMA	Repaired roof - main building, Flooring replaced - restrooms, Remodeled staff and boys/girls restrooms. Fixed all walls in restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development, Installed new 4 inch backflow and	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom repairs Painting Painting Replace 2 sets of double doors on main building. Cut down and remove dead tree Flooring. Backflow General repairs	Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Routine maintenance Safety. Already planned. Safety Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross connection reasons Safety	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 4,000.00 60,000.00 8,651.00 100,000.00 45,000.00 45,000.00 16,000.00 1,500.00 120.00 22,000.00 42,670.00 1,000.00 4,800.00	RRMA RRMA DM DM DM RRMA DM RRMA DM RRMA DM RRMA RAMA Bond	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Fixed all walls in restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring - Preschool, Installed new area drains between	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom repairs Painting Painting Painting Cut down and remove dead tree Flooring. Cut down and remove dead tree Flooring. Backflow General repairs Exterior repairs	Safety. Already planned. Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Routine maintenance Safety. Already planned. Safety Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross connection reasons Safety Safety Safety Safety	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700,00 28,000,00 1,600,00 8,100,00 8,000,00 8,000,00 8,000,00 8,651,00 100,000,00 45,000,00 11,000,00 120,00 22,000,00 1,000,00 42,670,00 1,000,00 48,000,00 48,000,00 48,000,00 48,000,00 48,000,00 8,000,00	RRMA DM DM DM RRMA DM RRMA DM RRMA DM RRMA RRMA	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Flixed all walls in restrooms. Painted front Administrative building. Painted flag ceramony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring - Preschool,	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom repairs Painting Painting Replace 2 sets of double doors on main building. Cut down and remove dead tree Flooring. Backflow General repairs	Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Safety. Already planned. Safety Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross connection reasons Safety Safety Safety Safety Safety Routine maintenance. Safety Safety Routine maintenance.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 8,000.00 60,000.00 100,000.00 45,000.00 15,000.00 120,000.00 1,500.00 1,000.00 4,670.00 4,670.00 4,670.00 4,600.00 4,600.00 4,600.00 4,600.00 4,600.00 4,600.00 4,600.00	RRMA DM DM DM RRMA DM RRMA DM RRMA RRMA	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring - Preschool. Installed new area drains between wings.	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Kynoch Kynoch	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield. Repave blacktop area Shade structure. Automation of field and front of school Roofing. Fitooring. Restroom repairs Painting Replace 2 sets of double doors on main building. Landscape field near new huilding. Cut down and remove dead tree Fiooring. Backflow General repairs Exterior repairs Exterior repairs Exterior repairs Install new water heater. Storm drain install. Backflow install.	Safety. Safety. Routine maintenance. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Safety. Already planned. Safety Routine maintenance Safety. Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross connection reasons Safety Safety Safety Routine maintenance	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 8,100.00 4,000.00 60,000.00 8,651.00 100,000.00 45,000.00 45,000.00 1,500.00 1,500.00 42,670.00 4,800.00 8,000.00 4,800.00 8,000.00 1,600.00 4,800.00 6,000.00 1,600.00 6,000.00	RRMA DM DM DM RRMA DM RRMA DM RRMA DM RRMA RRMA	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Fixed all walls in restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring - Preschool, Installed new area drains between	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Kynoch	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom repairs Painting Painting Replace 2 sets of double doors on main building. Cut down and remove dead tree Flooring. Backflow General repairs Exterior repairs Exterior repairs Exterior repairs Exterior repairs Exterior repairs	Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Safety. Already planned. Safety Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross connection reasons Safety Safety Safety Safety Safety Routine maintenance. Safety Safety Routine maintenance.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 8,000.00 60,000.00 100,000.00 45,000.00 15,000.00 120,000.00 1,500.00 1,000.00 4,670.00 4,670.00 4,670.00 4,600.00 4,600.00 4,600.00 4,600.00 4,600.00 4,600.00 4,600.00	RRMA DM DM DM RRMA DM RRMA DM RRMA RRMA	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Fixed all walls in restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring - Preschool. Installed new area drains between wings. Cal water compliance order. Johnson Controls is working with M2USD on implementation. Completion date	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Kynoch Kynoch Kynoch Linda Elementary	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase 2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom repairs Painting Painting Replace 2 sets of double doors on main building. Cut down and remove dead tree Flooring. Backflow General repairs Exterior repairs Exterior repairs Exterior repairs Exterior repairs Exterior school Exterior repairs Exterior repairs Exterior repairs Exterior repairs Linstall new water heater. Storm drain install. Backflow install. Put together oven. Delamp and relamp.	Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Safety. Already planned. Safety Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross connection reasons Safety Safety Routine maintenance, Routine maintenance we add this backflow to the site for cross connection reasons Safety Routine maintenance, Routine maintenance, Routine maintenance, Routine maintenance, Health and safety.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 8,000.00 8,000.00 60,000.00 8,651.00 100,000.00 45,000.00 15,000.00 120.00 22,000.00 4,600.00 4,600.00 1,000.00 4,600.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,000.00 1,600.00 1,600.00	RRMA RRMA DM DM DM RRMA DM RRMA Bond DM RRMA RRMA RMA Prop 39	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring - Preschool, Installed new area drains between wings. Cal water compliance order. Johnson Controls is working with M3USD	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Kynoch Kynoch Kynoch	Fencing, New cafeeria tables, Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blackton area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom repairs Painting Replace 2 sets of double doors on main building. Cut down and remove dead tree Flooring. Backflow General repairs Exterior repairs Exterior repairs Exterior repairs Exterior repairs Linstall new water heater. Storm drain install, Backflow install, Put together oven.	Safety. Safety. Routine maintenance. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Already planned. Safety. Already planned. Safety. Already planned. Safety. Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross connection reasons. Safety Safety Routine maintenance. Routine maintenance. Routine maintenance. Routine maintenance. Routine maintenance. Routine maintenance.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 8,000.00 8,000.00 8,000.00 8,651.00 100,000.00 45,000.00 45,000.00 120.00 120.00 22,000.00 4,600.00 4,600.00 1,000.00 4,600.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00	RRMA DM DM DM DM RRMA DM RRMA DM RRMA RRMA	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring - Preschool. Installed new area drains between wings. Cal water compliance order. Johnson Controls is working with MJUSD on implementation. Completion date Soring 2019. Flooring replaced - Preschool.	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Kynoch Kynoch Linda Elementary	Fencing. New cafeteria tables. Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing. Flooring. Restroom remodel. Restroom repairs Painting Painting Replace 2 sets of double doors on main building. Landscape field near new building. Cut down and remove dead tree Flooring. Backflow General repairs Exterior repairs Exterior repairs Install new water heater. Storm drain install. Backflow install. Put together oven. Delamp and relamp. Trim and thin mulberry trees	Safety. Routine maintenance. Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Routine maintenance Safety. Already planned. Safety. Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross connection reasons Safety Safety Routine maintenance, Routine maintenance, Routine maintenance, Routine maintenance, Routine maintenance, Routine maintenance, Health and safety.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700,00 28,000,00 1,600,00 8,100,00 8,100,00 4,000,00 60,000,00 8,651,00 100,000,00 45,000,00 15,000,00 15,000,00 120,000,00 15,000,00 120,000,00 1,500,00 1,500,00 1,500,00 1,500,00 1,600,00	RRMA RRMA DM DM RRMA DM RRMA RRMA Bond DM RRMA RRMA Bond Prop 39 General Fund.	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Fixed all walls in restrooms. Fixed all walls in restrooms. Painted find Administrative building. Painted find ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring Preschool. Installed new area drains between wings. Cal water compliance order. Johnson Controls is working with MJUSD on Implementation. Completion date Soring 2019. Flooring replaced - Preschool. Flooring replaced - Preschool. Flooring replaced - Preschool. Furred new walls and installed tack	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Kynoch Kynoch Kynoch Linda Elementary	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rip rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom remodel, Restroom repairs Painting Painting Replace 2 sets of double doors on main building. Landscape field near new tuilding. Cut down and remove dead tree Flooring. Backflow General repairs Exterior repairs Linstall new water heater. Storm drain install, Backflow install, Put together oven, Delamp and relamp. Trim and thin mulberry trees Flooring.	Safety. Safety. Routine maintenance. Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Safety. Already planned. Safety. Already planned. Safety. Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross connection reasons Safety Safety Routine maintenance. Routine maintenance. Health and safety. Prop 39 Project Safety. The flooring is beyond repair	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700.00 28,000.00 1,600.00 8,100.00 8,100.00 8,000.00 60,000.00 100,000.00 45,000.00 145,000.00 120,000.00 120,000.00 1,500.00 1,500.00 1,000.00 42,670.00 4,800.00 8,000.00 1,600.00	RRMA RRMA DM DM RRMA DM RRMA RRMA RRMA	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring - Preschool, Installed new area drains between wings. Cal water compliance order. Johnson Controls is working with M3USD on implementation. Completion date Soring 2019 Flooring replaced - Preschool. Furred new walls and installed tack board.	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Kynoch Kynoch Kynoch Linda Elementary Linda Elementa	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rup rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom repairs Painting Painting Replace 2 sets of double doors on main building. Landscape field near new building. Cut down and remove dead tree Flooring. Backflow General repairs Exterior repairs Linstall new water heater. Storm drain install. Backflow install. Put together oven. Delamp and relamp. Trim and thin mulberry trees Flooring. General repairs	Safety. Safety. Routine maintenance. Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Safety. Already planned. Safety. Already planned. Safety. Safety. Already planned. Safety Flooring is old and beyond repair Cal Water mandated we add this backflow to the site for cross connection reasons Safety Safety Routine maintenance. Routine maintenance. Routine maintenance. Health and safety. Prop 39 Project Safety The flooring is beyond repair Safety	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700,00 28,000,00 1,600,00 8,100,00 8,000,00 60,000,00 100,000,00 45,000,00 15,000,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00 1200,00	RRMA RRMA DM DM DM RRMA DM RRMA RRMA RR	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Fixed all walls in restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring - Preschool. Installed new area drains between winds. Cal water compliance order. Johnson Controls is working with MJUSD on implementation. Completion date Sorina 2019 Flooring replaced - Preschool. Flooring replaced - Preschool. Furred new walls and installed tack board. Remodeled library building. Cut all doors after new flooring -	Completed
Foothill Intermediate Johnson Park Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Elementary Kynoch Kynoch Kynoch Linda Elementary Linda Elementar	Fencing, New cafeteria tables, Pull up bars. Keystone block wall/phase1 Keystone block wall/phase2 Basketball hoops Rup rap Landscape playfield Repave blacktop area Shade structure. Automation of field and front of school Roofing, Flooring, Restroom remodel, Restroom remodel, Restroom repairs Painting Painting Replace 2 sets of double doors on main building. Cut down and remove dead tree Flooring. Backflow General repairs Exterior repairs Install new water heater. Storm drain install. Backflow install. Put together oven. Delamp and relamp. Trim and thin mulberry trees Flooring. General repairs	Safety. Lack of shade. No automation. Roof leaks Restrooms are old smelly and outdated. Safety. Routine maintenance Safety. Already planned. Safety Safety. Routine maintenance we add this backflow to the site for cross connection reasons Safety Routine maintenance, Routine maintenance, Routine maintenance, Routine maintenance, Routine maintenance, Health and safety. Prop 39 Project Safety Safety Safety Safety Safety Safety Site request	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,700,00 28,000,00 1,600,00 8,100,00 8,100,00 8,000,00 60,000,00 100,000,00 15,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 120,000,00 1200,	RRMA RRMA DM DM DM RRMA DM RRMA RRMA RR	Repaired roof - main building. Flooring replaced - restrooms. Remodeled staff and boys/girls restrooms. Painted front Administrative building. Painted flag ceremony area. Flooring replaced - Child Development. Installed new 4 inch backflow and moved to front of school next to meter box. Cut all doors after new flooring - Preschool, Installed new area drains between wings. Cal water compliance order. Johnson Controls is working with M3USD on implementation. Completion date Soring 2019 Flooring replaced - Preschool. Furred new walls and installed tack board.	Completed

Linda Elementary	Exterior repairs	Grounds request	\$	600,00	RRMA	Bulld and install new gate (north/west side). Too small for mowers.	Completed
Lindhurst High	Lighting improvements	Prop 39 funding via engineering Report and EEP	\$	7.1	Prop 39	Johnson Controls is working with MJUSD on implementation of Prop 39 projects. Completion date Spring 2019.	Completed
Lindhurst High	Flooring in portables	Carpet is beyond repair	\$	1,200.00	DM DM	Replaced flooring in portables. Roof repaired - room F.	Completed Completed
Lindhurst High Lindhurst High	Roofing.	Roof leaks Roof leaks	5	2,200.00	DM	Roof repaired - Building C.	Completed
Lindhurst High		Dry rot and damage is beyond	\$	44,000.00	DM	Repaired/replaced fascla boards and	Completed
Lindhurst High	Water heater	repair Leaks and is non operational	\$	2,400.00	RRMA	stucco – E Building. Installed new water heater in C Building and kitchen tankless.	Completed
Lindhurst High	Tollets	Tollets are old and beyond repair	\$	900.00	RRMA	Installed new high efficiency tollets in	Completed
				1,300.00	RRMA	staff restrooms - Building. Cafeteria doors and windows (frame and	Completed
Lindhurst High		Safety	\$			drywall).	
Lindhurst High	General repairs	Safety	\$	1,200.00	RRMA	Cafeteria wall (demo windows/door).	Completed
Undhurst High	Exterior repairs	Safety	\$	1,000.00	RRMA	Build and Install new gate (west side).	Completed
Lindhurst High	Drinking fountain.	Site request	\$	2,000.00 400.00	DM	Installed new drinking fountain.	Completed Completed
Lindhurst High Lindhurst High	Fix cyclone fencing gym area. 4 Seasons HVAC fix.	Safety.	5	45,000.00			Completed
Lindhurst High	Install drinking fountain/tennis	Compliance.	\$	1,600.00			Completed
Lindhurst High	courts. OPUD flush water lines	Health and safety.	5				Completed
Undhurst High	Wrought iron fencing	Safety.	\$	45,000.00			Completed
Lindhurst High	Sheetrock Aq building	Site request.	\$	1,500.00	00144		Completed
Lindhurst High Lindhurst High	Replace recert pump/qym Greenhouse gas main	Safety.	5	3,200.00	RRMA RRMA		Completed Completed
Lindhurst High	Add bollards.	Safety.	5	9,000.00	100.01		Completed
Lindhurst High	Culinary kitchen	CTE grant; Improve program resources.	\$	40,498.00	CTE		Completed
Lindhurst High	Frontage fencing	Curb appeal.	\$	43,100.00	Deferred Maintenance		Completed
Lindhurst High	Stucco building C	Failing system.	\$	44,000.00	RRMA General Fund		Completed
Lindhurst High	HVAC Increment #2	Falling system; project already	1	2,100,000.00	One-Time		Completed
Lindhurst High	Replace all exterior lighting with	planned. Safety.	\$	6,000.00	RMAA		Completed
	LED		1		Deferred		Completed
Lindhurst High	Re landscape football field	Safety.	\$	275,000.00	Maintenance		
Lindhurst High	Front office renovation	Safety, Safety.	\$	15,000.00	RMAA		Completed Completed
Lindhurst High Lindhurst High	Weld shop renovation. Paint buildings,	Routine Maintenance.	1	7,000.00	RRMA		Completed
Loma Rica Elementary	Water treatment	Safety	\$	3,000.00	RRMA	New water treatment system installed.	Completed
Loma Rica Elementary	Exterior repairs	Safety		N/A	N/A	Skunk proofed Admin building.	Completed
Loma Rica Elementary	Painting	Routine maintenance	\$	1,000.00	RRMA	Lower parking lot area.	Completed
Marysville High	Roof repair	Roof leaking	5	1,200.00	DM	Roof repaired - weight room.	Completed
Marysville High	Flooring.	Flooring is outdated and beyond	\$	1,600.00	DM	Replaced flooring in Coach's office.	Completed
Marysville High	Plumbing repairs.	Will not flush and backs up	\$	900.00	RRMA	Fixed plumbing and replaced urinal in staff room.	Completed
		Kids do not have a place to wash	+-				
IManucullo High	New clak pooded		I 4	1.800:00	RRMA	Added new sink in Ag Department - pig	Completed
Marysville High	New sink needed	their hands	\$	1,800.00	RRMA	pens.	Completed
Marysviife High	Lighting	their hands Routine Maintenance	Ė		RRMA	pens. Change library lights.	Completed
Marysville High Marysville High	Lighting Fencing	their hands Routine Maintenance Safety	\$	1,200.00	RRMA MHS	pens. Change library lights. Installed Ag fencing around rose garden.	Completed Completed
Marysville High Marysville High Marysville High	Lighting Fencing Roof repair.	their hands Routine Maintenance Safety leaking	\$	1,200.00	RRMA MHS DM	pens. Change library lights.	Completed Completed Completed
Marysville High Marysville High Marysville High Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect spacer, field lighting Worked w/Berry Electric -	their hands Routine Maintenance Safety leaking Safety.	\$ 5	1,200.00 2,800.00 4,000.00	RRMA MHS DM RRMA	pens. Change library lights. Installed Ag fencing around rose garden.	Completed Completed Completed Completed
Marysville High Marysville High Marysville High Marysville High Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect spacer, field lighting Worked w/Berry Electric - program VFD for Irrigation pump	their hands Routine Maintenance Safety leaking Safety. Failing system.	\$	1,200.00 2,800.00 4,000.00 3,000.00	RRMA MHS DM RRMA	pens. Change library lights. Installed Ag fencing around rose garden.	Completed Completed Completed Completed Completed
Marysville High Marysville High Marysville High Marysville High Marysville High Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for irrigation pump Repair/replace all exit signs	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety.	\$ 5	1,200.00 2,800.00 4,000.00 3,000.00	RRMA MHS DM RRMA RMAA RRMA	pens. Change library lights. Installed Ag fencing around rose garden.	Completed Completed Completed Completed Completed Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect spacer, field lighting Worked w/Berry Electric - program VFD for Irrigation pump	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety, Safety, Safety,	\$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00	RRMA MHS DM RRMA RMAA RRMA RRMA	pens. Change library lights. Installed Ag fencing around rose garden.	Completed Completed Completed Completed Completed Completed Completed Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS audfordum Hook up new C & C machine/woodshop	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety. Safety. Safety. Safety. Safety.	\$ 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA	pens. Change library lights. Installed Ag fencing around rose garden.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect spaces field lighting Worked w/Berry Electric - program VFD for irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety, Safety, Safety, Safety, Safety, Safety,	\$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00	RRMA MHS DM RRMA RMAA RRMA RRMA	pens. Change library lights. Installed Ag fencing around rose garden.	Completed Completed Completed Completed Completed Completed Completed Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/HHS audtorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board Install	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety, Safety, Safety, Safety, Safety Sifety Sife	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,100.00 130,000.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA	pens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric program VFD for irrigation pump Repair/roplace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board Install Sports med room	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety. Safety. Safety. Safety. Safety. Safety. CTE grant; improve program resources.	\$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,100.00 130,000.00	RRMA MHS DM RRMA RMAA RMAA RRMA RRMA RRMA RRMA	pens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/HHS audtorhum Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors.	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety, Safety, Safety, Safety, Care y, Safety, Care grant; improve program resources. Routine Maintenance. Routine Maintenance. Routine Maintenance.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 1,200.00 1,100.00 130,000.00 120,000.00 12,000.00 3,000.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	pens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect speccer field lighting Worked w/Berry Electric - program VFD for irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater - staff	their hands Routine Maintenance Safety leaking Safety. Failing system. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance. Routine Maintenance. Routine Maintenance.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 130,000.00 120,000.00 12,000.00 1,200.00 1,200.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	pens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect spaces field lighting Worked w/Berry Electric - program VFD for irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater - staff Boys locker room partition	their hands Routine Maintenance Safety leaking Safety, Falling system. Safety, Safety, Safety, Safety, Sifety Site project. CTE grant; improve program resources. Routine Maintenance. Routine Maintenance. Routine Maintenance. Routine Maintenance.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 1,200.00 1,100.00 130,000.00 120,000.00 12,000.00 3,000.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	pens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer, field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board Install Sports med room Paint gym floors. Water heater install "C" Water heater - staff Boys locker room partition Field house lighting Stadium lights disconnects	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance, Routine Maintenance, Safety,	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,100.00 130,000.00 120,000.00 1,200.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	pens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect spaces. Field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board Install Sports med room Paint gym floors. Water heater install "C" Water heater - staff Boys locker room partition Field house lighting Stadium lights disconnects Football pad installation	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety. Safety. Safety. Safety. Sifety. Sifety. Site project. CTE grant; Improve program resources. Routine Maintenance. Routine Maintenance. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety.	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 130,000.00 120,000.00 1,200.00 4,000.00 4,000.00 4,000.00 34,000.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	pens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer, field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board Install Sports med room Paint gym floors. Water heater install "C" Water heater - staff Boys locker room partition Field house lighting Stadium lights disconnects	their hands Routine Maintenance Safety leaking Safety, Falling system. Safety, Safety, Safety, Safety, Sifety, Sifety, Sifety, Site project, CTE grant; improve program resources. Routine Maintenance, Routine Maintenance, Routine Maintenance, Safety,	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,100.00 130,000.00 120,000.00 1,200.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00	RRMA MHS DM RRMA RMAA RMAA RRMA RRMA RRMA RRMA R	pens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect spaces. Field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board Install Sports med room Paint gym floors. Water heater install "C" Water heater - staff Boys locker room partition Field house lighting Stadium lights disconnects Football pad installation	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance. Routine Maintenance. Safety. Safety. Safety. Safety. Safety. Safety. Safety. CTE grant; improve program resources.	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 130,000.00 120,000.00 1,200.00 4,000.00 4,000.00 4,000.00 34,000.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	pens. Change library lights: Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board Install Sports med room Paint gym floors. Water heater install "C" Water heater staff Boys locker room partition Field house lighting Stadium lights disconnects Football pad installation Tree removal Revamp lemon tree room	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety, Safety, Safety, Safety, Sifety, Safety, Sifety, Sifet	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,100.00 130,000.00 120,000.00 1,200.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	Dens. Change library lights: Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. Installed water bottle fill station. MCAA provided bottle filling station and maintenance installed.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric program VFD for irrigation pump Repair/roplace all exit signs Relabel panel/MHS audtorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater - staff Boys locker room parition Field house lighting Stadium lights disconnects Football pad installation Tree removal Revamp lemon tree room	their hands Routine Maintenance Safety leaking Safety. Safety. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance. Routine Maintenance. Routine Maintenance. Safety.	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 1,200.00 1,200.00 130,000.00 120,000.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 4,000.00 1,000.00	RRMA MHS DM RRMA RMAA RMAA RRMA RRMA RRMA RRMA R	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. Installed water bottle fill station. MCAA provided bottle filling station and maintenance installed. Installed maintenance installed. Installed maintenance installed.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board Install Sports med room Paint gym floors. Water heater install "C" Water heater staff Boys locker room partition Field house lighting Stadium lights disconnects Football pad installation Tree removal Revamp lemon tree room	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety, Safety, Safety, Safety, Sifety, Safety, Sifety, Sifet	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,000.00 120,000.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 4,000.00 1,000.00 1,000.00 4,000.00 1,000.00 1,000.00 1,000.00 4,000.00 1	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA CTE Grant Site RRMA RRMA RRMA RRMA RRMA RRMA RRMA RRM	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. Installed water bottle fill station. MCAA provided bottle filling station and maintenance installed. Installed new irrigation backflow. Build frame above buildings (for banners XMCAA) graduation.	Completed
Marysville High	Lighting Fencing Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric program VFD for Irrigation pump Repair/roplace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board Install Sports med room Paint gym floors. Water heater install "C" Water heater install "C" Water heater staff Boys locker room parittion Frield house lighting Stadium lights disconnects Football pad installation Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance, Routine Maintenance, Safety. Safety. Safety. Safety. Safety. CTE grant; improve program resources. Kids do not have a place to fill their water bottles. Safety.	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 120,000.00 120,000.00 1,200.00 1,200.00 1,200.00 4,000.00 13,000.00 4,000.00 13,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 13,000.00 4,000.00 13,000.00 4,000.00 13,000.00 13,000.00 13,000.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. Installed water bottle fill station, MCAA provided bottle filling station and maintenance installed. Installed new irrigation backflow, Build frame above buildings (for banners VMCAA graduation. Stage addition.	Completed
Marysville High MCAA	Lighting Fencing Roof repair. Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater install "C" Water heater staff Boys locker room partition Fleid house lighting Stadium lights disconnects Football pad installation. Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow Frame sign	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance. Routine Maintenance. Safety. Safety. Safety. Safety. Safety. CTE grant; improve program resources. Kids do not have a place to fill their water bottles. Safety.	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,000.00 120,000.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 4,000.00 1,000.00 1,000.00 4,000.00 1,000.00 1,000.00 1,000.00 4,000.00 1	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA CTE Grant Site RRMA RRMA RRMA RRMA RRMA RRMA RRMA RRM	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. Installed water bottle fill station. MCAA provided bottle filling station and maintenance installed. Installed new irrigation backflow. Build frame above buildings (for banners)/MCAA or draduation. Stage addition. New HVAC unit installed - multipurpose room.	Completed
Marysville High	Lighting Fencing Roof repair. Roof repair. Remove/replace disconnect seccer field lighting Worked w/Berry Electric - program VFD for irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater staff Boys locker room partition Field house lighting Stadium lights disconnects Football pad installation Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow Frame sign Stage,	their hands Routine Maintenance Safety leaking Safety. Safety. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance. Routine Maintenance. Routine Maintenance. Safety. Siafety. Site request HAVC unit has failed and is	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 120,000.00 120,000.00 1,200.00 1,200.00 1,200.00 4,000.00 13,000.00 4,000.00 13,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 13,000.00 4,000.00 13,000.00 4,000.00 13,000.00 13,000.00 13,000.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. Installed water bottle fill station. MCAA provided bottle filling station and maintenance installed. Installed new irrigation backflow. Build frame above buildings (for banners J/NCAA graduation. Stage addition. New HVAC unit installed - multipurpose room. Replaced concrete after broken pipe was Replac	Completed
Marysville High McAA McAA McAA McAA McAA McAA McAA McKenney Intermediate	Lighting Fencing Roof repair. Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater staff Boys locker room partition Field house flighting Stadium lights disconnects Football pad installation Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow Frame sign Stage; HVAC unit replacement.	their hands Routine Maintenance Safety leaking Safety. Safety. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance. Routine Maintenance. Safety. Safety. Safety. CTE grant; improve program resources. Kids do not have a place to fill their water bottles. Safety.	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,200.00 120,000.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 4,000.00 1,000.00 1,000.00 4,000.00 1,000.00 4,000.00 1,000.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA CTE Grant Site RRMA RRMA RRMA RRMA RRMA RRMA RRMA RRM	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. Installed water bottle fill station. MCAA provided bottle filling station and maintenance installed. Installed new irrigation backflow. Build frame above buildings (for banners)/MCAA or draduation. Stage addition. New HVAC unit installed - multipurpose room.	Completed
Marysville High McAA MCAA MCAA MCAA MCAA MCAA MCKenney Intermediate McKenney Intermediate	Lighting Fencing Roof repair. Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater install "C" Water heater staff Boys locker room partition Fleid house lighting Stadium lights disconnects Football pad installation. Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow Frame sign Stage. HVAC unit replacement. Exterior repairs	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; Improve program resources. Routine Maintenance. Routine Maintenance. Safety. Site request Site request Site request Site request Site request Safety Safety Site request Site request Site request Site request Safety	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 120,000.00 120,000.00 1,200.00 1,200.00 1,200.00 4,000.00 130,000.00 4,000.00 4,000.00 4,000.00 4,000.00 4,000.00 13,000.00 4,000.00 13,000.00 4,000.00 4,000.00 400.00 800.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. In progress of the prog	Completed
Marysville High McAA MCAA MCAA MCAA MCAA MCAA MCKenney Intermediate McKenney Intermediate McKenney Intermediate McKenney Intermediate McKenney Intermediate McKenney Intermediate	Lighting Fencing Roof repair. Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater install "C" Water heater staff Boys locker room partition Fleid house lighting Stadium lights disconnects Football pad installation. Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow Frame sign Stage, HVAC unit replacement. Exterior repairs Replace gym doors. Flooring.	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance. Routine Maintenance. Routine Maintenance. Safety. Safety Site request Site request HAVC unit has failed and is beyond repair	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 120,000.00 120,000.00 1,200.00 4,000.00 130,000.00 130,000.00 4,000.00 130,000.00 4,000.00 25,000.00 400.00 400.00 800.00 1,500.00 800.00 9,000.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. In progress. Estimated Jan 2018. In progress Jan 2018. In progress	Completed
Marysville High Mcraysville High Marysville High Marysv	Lighting Fencing Roof repair. Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater install "C" Water heater staff Boys locker room partition Field house flighting Stadium lights disconnects Football pad installation Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow Frame sign Stage; HVAC unit replacement. Exterior repairs Replace gym doors. Flooring Flooring	their hands Routine Maintenance Safety leaking Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; Improve program resources. Routine Maintenance. Routine Maintenance. Safety. Safety Slite request Site request	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,200.00 130,000.00 120,000.00 1,200.00 1,200.00 4,000.00 1,200.00 4,000.00 1,000.00	RRMA MHS DM RRMA RMAA RMAA RRMA RRMA RRMA RRMA R	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. In progress. Estimated completion Jan 2018. Installed water bottle fill station. MCAA provided bottle filling station and maintenance installed. Installed new irrigation backflow. Build frame above buildings (for banners INFACA graduation. Stage addition. Replaced concrete after broken pipe was repaired. Doors have been installed. Flooring replaced - rooms 23, 24 & 25. Flooring replaced - restrooms.	Completed
Marysville High McAA McAA McAA McAA McAA McAA McAA McKenney Intermediate McKenney Intermediate McKenney Intermediate McKenney Intermediate McKenney Intermediate	Lighting Fencing Roof repair. Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater install "C" Water heater staff Boys locker room partition Fleid house lighting Stadium lights disconnects Football pad installation. Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow Frame sign Stage, HVAC unit replacement. Exterior repairs Replace gym doors. Flooring.	their hands Routine Maintenance Safety leaking Safety. Falling system. Safety. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance, Routine Maintenance, Routine Maintenance, Safety. Safety Safety Site request Site request Site request Site request Flooring is old and beyond repair Flooring is old and beyond repair	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 12,000.00 120,000.00 1,200.00 1,500.00 1,500.00 1,500.00 1,500.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. In progress. Estimated completion Jan 2018. In provided bottle fill station. MCAA provided bottle filling station and maintenance installed. Installed new irrigation backflow, Build frame above buildings (for banners INFACA graduation. Stage addition. New HVAC unit installed - multipurpose room. Replaced concrete after broken pipe was repaired. Doors have been installed. Flooring replaced - rooms 23, 24 & 25.	Completed
Marysville High Mcraysville High Marysville High Marysv	Lighting Fencing Roof repair. Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater install "C" Water heater staff Boys locker room partition Field house flighting Stadium lights disconnects Football pad installation Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow Frame sign Stage; HVAC unit replacement. Exterior repairs Replace gym doors. Flooring Flooring	their hands Routine Maintenance Safety leaking Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; Improve program resources. Routine Maintenance. Routine Maintenance. Safety. Safety Slite request Site request	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,200.00 130,000.00 120,000.00 1,200.00 1,200.00 4,000.00 1,200.00 4,000.00 1,000.00	RRMA MHS DM RRMA RMAA RMAA RRMA RRMA RRMA RRMA R	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. In progress. Estimated completion Jan 2018. Installed water bottle fill station. MCAA provided bottle filling station and maintenance installed. Installed new irrigation backflow. Build frame above buildings (for banners INFACA graduation. Stage addition. Replaced concrete after broken pipe was repaired. Doors have been installed. Flooring replaced - rooms 23, 24 & 25. Flooring replaced - restrooms.	Completed
Marysville High McAaysville High McAa McCAA McCAA McCAA McCAA McCAA McCAA McKenney Intermediate Olivehurst Elementary Olivehurst Elementary	Lighting Fencing Roof repair. Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/replace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board install Sports med room Paint gym floors. Water heater install "C" Water heater install "C" Water heater install Sports med room Paint gym floors. Water heater install "C" Water heater install "C" Water heater install "C" Water heater on martition Field house flighting Stadium lights disconnects Football pad installation Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow Frame sign Stage; HVAC unit replacement. Exterior repairs Replace gym doors. Flooring Flooring Flooring	their hands Routine Maintenance Safety leaking Safety. Safety. Safety Site request Site request Site request Site request Flooring is old and beyond repair Staff and students are flushing Feminine hygiene products into the sewer which is being sucked into the pumps and burning them Restroom smells of urine and is beyond cleaning. Plumbing	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,100.00 120,000.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 4,000.00 1,000.00 4,000.00 4,000.00 4,000.00 4,000.00 1,000.00 4,000.00 4,000.00 4,000.00 1,500.00 8,000.00 1,500.00 8,000.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00	RRMA MHS DM RRMA RMAA RRMA RRMA RRMA RRMA RRMA R	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. Installed water bottle fill station. MCAA provided bottle filling station and maintenance Installed. Installed new irrigation backflow. Build frame above buildings (for banners I/MCAA graduation. Stage addition. New HVAC unit installed - multipurpose room. Replaced concrete after broken pipe was repaired. Doors have been installed. Flooring replaced - rooms 23, 24 & 25. Flooring replaced - restrooms. Flooring replaced - Preschool. Replaced 2 septic pumps in lift station.	Completed
Marysville High McAA MCAA MCAA MCAA MCAA MCAA MCAA MCAA	Lighting Fencing Roof repair. Roof repair. Remove/replace disconnect soccer field lighting Worked w/Berry Electric - program VFD for Irrigation pump Repair/roplace all exit signs Relabel panel/MHS auditorium Hook up new C & C machine/woodshop Provide Power to new freezer Score board Install Sports med room Paint gym floors. Water heater - staff Boys locker room partition Frield house lighting Stadium lights disconnects Football pad installation Tree removal Revamp lemon tree room Water bottle fill station Irrigation backflow Frame sign Stage, HVAC unit replacement. Exterior repairs Replace gym doors. Flooring Flooring Flooring Septic pumps	their hands Routine Maintenance Safety leaking Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Safety. Site project. CTE grant; improve program resources. Routine Maintenance. Routine Maintenance. Routine Maintenance. Safety. Safety. Safety. Safety. Safety. CTE grant; improve program resources. Kids do not have a place to fill their water bottles. Safety Site request Site request Site request Flooring is old and beyond repair Staff and students are flushing feminine hygiene products into the sewer which is being sucked into the pumps and burning them in. Restroom smells of urine and is	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1,200.00 2,800.00 4,000.00 3,000.00 6,000.00 1,200.00 1,100.00 120,000.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 1,200.00 4,000.00 1,000.00 4,000.00 4,000.00 4,000.00 4,000.00 1,000.00 4,000.00 4,000.00 4,000.00 1,500.00 8,000.00 1,500.00 8,000.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00 1,500.00	RRMA MHS DM RRMA RMAA RMAA RRMA RRMA RRMA RRMA R	Dens. Change library lights. Installed Ag fencing around rose garden. Roof repaired - cafeteria. In progress. Estimated completion Jan 2018. But a provided bottle filling station and maintenance installed. But a provided bottle filling station and maintenance installed. But a provided bottle filling station backflow. Replaced concrete after broken pipe was renaired. Boors have been installed. Flooring replaced - rooms 23, 24 & 25. Flooring replaced - restrooms. Flooring replaced - Preschool. Replaced 2 septic pumps in lift station. Provided site with in stall garbage cans. Remodeled restrooms in kinder room	Completed

Olivehurst Elementary	General repairs	Safety		N/A	N/A	Cut all doors after new flooring.	Completed
Olivehurst Elementary		Site beautification	\$	2,600.00	RRMA	All doors, handralls, handball courts, lower gutters on main entry ways, four squares, door safety barriers, outside kitchen area.	Completed
Olivehurst Elementary	Landscape field near new building	Already planned	\$	45,000.00	Bond		Completed
Olivehurst Elementary	Restroom update						Completed
Ollvehurst Elementary	Widen driveway at new traffic	County of Yuba request for traffic and safety	\$		N/A		Completed
Tooth Mobile	Plumbing repairs.	Support by providing service when possible. Plumbing keeps backing up.	\$	500.00	Site	Repaired discharge on compressor into tank and added new clean out on discharge pump.	Completed
Yuba Feather Elementary	Landscape space between preschool playground and K-6 playground	Inadequate play space	\$	20,553.00	DM	Add sod, drip irrigation system, wood chip area, sandbox, trees and shrubs. Summer 2018.	Completed
Yuba Feather Elementary	HVAC unit replacement.	HVAC unit is old and beyond repair	\$	5,600.00	DM	New HVAC unit Installed - library.	Completed
Yuba Feather Elementary	General repairs.	Safety	\$	300.00	RRMA	Installed erosion netting,	Completed
Yuba Feather Elementary	Exterior repairs	Safety	5	1,600.00	DM	Rock and matting - drainage ditch.	Completed
Yuba Gardens Intermediate	Flooring	Floor is beyond repair. Needs replaced	\$	6,700.00	DM	Installed flooring in main office.	Completed
Yuba Gardens Intermediate	Door repair	Door is beyond repair. Needs replaced	\$	2,600.00	DM	Door replaced - front office.	Completed
Yuba Gardens Intermediate		FIT Inspections	\$	350.00	RRMA	Room 17, portable doors, all fit inspections - stained celling tiles.	Completed

	FMP Tier 1	Projects Bui	ldings & Gr	rounds	
School Site	Project	Estimated Cost	Funding Source	Notes	Status
Arboga Elementary	Fire alarm components upgrade,	\$ 39,420.00		Received estimate. Electrical capacity is an issue. Capacity is not	Hold
Arboga Elementary	Parking lot lighting.	\$ 30,000.00	TBD	a part of the arc flash study. Arc flash is related to safety. Need to hire an electrical engineer to assess. Added service and or panel is likely plus other materials like cobra heads or wall packs.	Hold
Arboga Elementary	Parking inadequate (grade and pave the gravel parking area).	\$ 30,000.00		If project is completed by contractor price will be approximately \$145,000.	Hold
Arboga Elementary	Ramps and rails at portable classrooms,	\$ -		Cost dependent upon District ADA study.	Hold
Arboga Elementary	Renovate restrooms for ADA compliance.	\$ 348,200.00		Cost based on Edgewater budget and scope. Cost dependent upon District ADA study.	Hold Hold
Browns Valley Elementary Browns Valley Elementary	ADA path of travel paving/walkways. Fire alarm components upgrade.	\$ 50,000.00			Hold
Browns Valley Elementary Browns Valley Elementary	Path of travel paying/walkways. Renovate building interior for ADA compliance.	\$ -	-	Cost dependent upon District ADA study. Cost dependent upon District ADA study.	Hold Hold
Cedar Lane Elementary	ADA compliance and upgraded doors and hardware replacement. (Throughout).	\$ =		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Cedar Lane Elementary	ADA study dueverify ADA compilance throughout.	\$ -		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Cedar Lane Elementary	Intercom/clocks system upgrade.	\$ 16,000.00		Assumes use of current speakers and clocks. If replacement needed, a survey would be required to determine total cost.	Hold
Cedar Lane Elementary	Security camera system Install,	\$ 85,000.00		To Install cameras to provide ample coverage throughout.	Hold
Cordua Elementary	ADA compliant renovation of building Interior.	\$ =		Cost dependent upon District ADA study, Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Cordua Elementary	ADA path of travel paving/walkways.	\$ =		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Cordua Elementary	Fire alarm components upgrade.	\$ 23,070.00		Received Est.	Hold
Cordua Elementary	Lead paint remediation as needed (analysis needed).	\$ 12,000.00		Received estimate.	Hold
Cordua Elementary	Lunch shelter - center of enclosed outdoor area,	\$ 110,000.00		Cost estimate based on LHS, Cost depends on size and other variables.	Hold
Cordua Elementary	Path of travel paving/walkways.	\$		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	
Covillaud Elementary	ADA compliance throughout campus.	\$ -		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to	Hold
Covillaud Elementary	ADA compliant classroom sinks and drinking fountains/bubblers in older classrooms.	\$		follow in fall/winter 2017. Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Covillaud Elementary	ADA compliant renovation of restrooms. Upgrade all fixtures, flooring, and tile.	\$		Cost dependent upon District ADA study, Site visits to take place in summer 2017, Report with findings and cost estimates to follow in fall/winter 2017.	Hold:
Covillaud Elementary	ADA ramps and ralls at portable classrooms.	\$ 12.0		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Heid
Covillaud Elementary	Administration - main office/entrance non-ADA-compliant and provides inadequate office space for 3 staff persons and principal. Need new administration/ilbrary/media center building with staff restrooms and workrooms/conference rooms and custodial space.	\$		Cost dependent upon District ADA study.	Hold
Covillaud Elementary	Electrical system upgrade circuit capacity in teachers' workroom possibly add circuit to avoid existing overload at copier machine and kitchen appliances when in use.	\$ 25,000.00			Hold
Covillaud Elementary	Replace portable classrooms with permanent/modular classrooms.	\$		14 Modular buildings. Cost estimate is to be determined via American Modular and site work, and dependent upon utilities, server, and electrical capacity (plus soft costs). Removal per building estimated at approximately \$16,000. Permanent classrooms would be a classroom building, which is a major facilities project and the cost estimate would be determined by scope.	Moid
Covillaud Elementary	Shade structures at K playground and at primary playground.	\$ 110,000.00			Hold
District Support	ADA Compliance throughout.	\$ 64,500.00		Cost dependent upon District ADA Study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
District Support	Drainage throughout	\$ -	-	3	
District Support	Electrical system capacity/safety upgrade.	\$ 200,000.00		Cost is for arc flash study and minor repairs only; currently gathering proposals and data. Electrical shut down for each site will be needed. Electrical capacity study needed separately. Capacity is not part of the arc flash study. The arc flash study is for safety and is required.	Hold
Dobbins Elementary	New regrading and paving on parking lot.	\$ 120,000.00		Needs contractor estimate.	Hold
Dobbins Elementary	Ramps and rails at portable classrooms.	\$		Cost dependent upon District ADA study.	Hold
Dobbins Elementary	Walkway at portable classrooms.	\$ -		Cost dependent upon District ADA study. Cost dependent upon District ADA study.	Hold
Ella Elementary	ADA Compliance throughout campus at older buildings.	\$ ==		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold

Ella Elementary	ADA hardware and doors on older buildings.	\$	Cost dependent upon District ADA study, Site visits to take place in summer 2017, Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Ella Elementary	General major modernization and ADA compliance throughout restrooms.	\$	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Note
Ella Elementary	Improve/expand food service capabilities, Larger cafeteria needed.	\$	Major facilitles project; Would need full design to determine cost.	Hold
Ella Elementary	Pathway/wheelchair access on stage.	\$	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Foothill Intermediate	ADA compilance throughout campus (verify through ADA plan).	\$ 25	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Foothill Intermediate	ADA compliant drinking fountains.	\$ 6,000.00		Hold
Foothill Intermediate	ADA compliant parking lot signage.	\$	Cost dependent upon District ADA study, Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Foothill Intermediate	ADA compliant parking lot striping.	\$	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017. May be addressed under path of travel improvements for Foothili shade canopy project.	etold
Foothill Intermediate	ADA compliant room and building signage (with Braille).	\$	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Foothill Intermediate	ADA hardware and doors throughout campus.	\$	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fail/winter 2017.	Hold
Foothill Intermediate	Add ADA lift at stage.	\$	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Foothill Intermediate	Demolish/replace/reconfigure most interior classroom walls, doors, and path of travel. There are many half-walls, non- compliant walls on wheels and other non-compliant construction issues.	\$	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Foothill Intermediate	Electrical system capacity/safety upgrade.	\$ 70,000.00	Electrical capacity study needed separately. Capacity is not part of the arc flash study. The Arc flash study is for safety and is regulred.	Note
Foothill Intermediate	Remove and replace folding and non-compliant walls.		Major facilities project; would need full	Hold
Johnson Park Elementary	ADA compliant renovation of restrooms. Upgrade all fixtures, flooring, and tile.	\$ (9)	design to determine cost. Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Johnson Park Elementary	ADA compilant sinks and drinking fountains in permanent classrooms.	\$ 82	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Held
Johnson Park Elementary	ADA hardware and sink needed at portables.	\$	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Johnson Park Elementary	Fire alarm components upgrade,	\$ 15,000.00 \$ 8,000.00	#5938	Hold
Johnson Park Elementary Kynoch Elementary	Lead paint remediation as needed (analysis needed). ADA compliant renovation of restrooms. Upgrade all fixtures, flooring, and tile.	\$ 8,000.00	#5930 Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Kynoch Elementary	ADA compliant sinks and drinking fountains in permanent classrooms.	\$ 700	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Kynoch Elementary	Fire alarm components upgrade. Improve food service capabilities.	\$ 15,000.00	Large scope project,	Hold Hold
Kynoch Elementary Kynoch Elementary	Ramps and rails at portable classrooms.	\$	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Kynoch Elementary	Renovate library.	\$	Major facilities project; would need full	Hold
Kynoch Elementary	Water system upgrade/pipe upgrade.	\$ 550,000.00	design to determine cost. Need more information,	Hold
Linda Elementary	ADA compliance for staff restrooms and general upgrade.	\$ 10,000.00	Work order #5684 - large scope.	Hold
Linda Elementary	ADA compliance for student restrooms and general upgrade of fixtures, sinks, walls, tiles, lighting, and ventilation.	\$ 13,000.00	Work order #5685/not what Principal asked for. Cost dependent upon District ADA study.	Hold
Linda Elementary	ADA compliant ramps and rails at portables.	\$	Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017. Cost dependent upon District ADA study.	Hold
Linda Elementary	ADA compliant and upgraded doors and hardware replacement (throughout).	\$:=:	Site visits to take place in summer 2017- Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Linda Elementary	ADA compliant sinks and drinking fountains in permanent classrooms.	\$	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Linda Elementary	ADA study due. Verify ADA compliance - path of travel, drinking fountains, door transitions, and restrooms.	\$ 300	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	нов.
Linda Elementary	Programmatic K-Pod Reconfigure pod/open classrooms/demolish unusable, non-compliant mezzanines.	\$	Major facilities project; would need full design to determine cost.	Hold

Linda Elementary	Security camera system install at rear of school.	\$	15,000.00	Just the rear of campus is \$15,000. Entire school would be approximately \$70,000.	Hold
Linda Elementary	Site storm drainage system upgrades needed,	\$	50,000	Work order #5686 - large scope project.	Hold
Lindhurst High	ADA compliant renovation of restrooms. Upgrade all fixtures, flooring, and tile.	\$	840		Hold
Lindhurst High	ADA compliant sinks and drinking fountains in permanent classrooms.	\$	100	Cost dependent upon District ADA study, Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Lindhurst High	ADA path of travel paving/walkways.	\$	*	Some ADA Improvements completed with quad and HVAC replacement projects 2015- 17. Other needed costs for further compliance determined via District ADA study.	Hold
Lindhurst High	Fire alarm components upgrade.	\$	30,000.00		Hold
Lindhurst High	New gymnaslum.	\$	38.5	Major facilities project; would need full design to determine cost.	Hold
Lindhurst High	ADA path of travel paving/walkways.	\$	9 4 0	Some ADA Improvements completed with quad and HVAC replacement projects. Other needed costs for further compliance determined via District ADA study.	Hold
Lindhurst High	Ramps and ralls at portable classrooms.	\$	٠	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Lindhurst High	Visitor entry controlled access.	\$		More information needed on design.	Hold
Loma Rica Elementary	ADA compliant new fencing and gate. Relocate and redesign main walkway, security, and visitor access.	\$	*	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Loma Rica Elementary	ADA door hardware In 3 older portables (If not replaced with new modular classrooms).	\$	N70	Cost dependent upon District ADA study, Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Loma Rica Elementary	ADA sink and hardware in 3 older portables (If not replaced with new modular classrooms).	\$	540	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Loma Rica Elementary	Drinking fountains.	\$	~	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Loma Rica Elementary	Fire alarm components upgrade.	\$	15,000.00		Hold
Loma Rica Elementary	Path of travel/transitions at all rooms and classrooms.	\$	*	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Loma Rica Elementary	Path of travel/paving/walkways.	\$	20	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Loma Rica Elementary	Permanent wall to replace construction barriers at street corner and along road (CMU Wall) fast traffic/very close to classrooms.	\$	35.1		Motd
Loma Rica Elementary	Ramps and rails in 3 older portables (if not replaced with new modular classrooms).	\$	350	See replacement Item below.	Hold
Loma Rica Elementary	Renovate restrooms for ADA compliance.	\$		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fail/winter 2017.	Hold
Loma Rica Elementary	Replace 3 older portables with new modular classrooms reconfigure with new site drainage and retaining walls to ensure storm water flow is adequately diverted throughout campus.	\$ 4	48,125.00	3 Modular buildings costs estimate is to be determined via American Modular plus site work and dependent on utilities, server and electrical capacity (plus soft costs). Removal per building estimated at approximately \$16,000. Permanent classrooms would be a classroom building, which is a major facilities project and the cost estimate would be determined by scope. Soil mitigation may be a factor. May require reconfigured placement.	Note:
Marysville Charter Academy	New performing arts theatre to provide ADA compliance.	\$	5=5		Hold
Marysville High	New team/weight room.	\$	47	Major facilities project; Would need full design to determine cost.	Hold
Marysville High	New gymnasium flooring.	\$ 4	20,000.00	School painting floor stripping in interim over Thanksgiving break. (\$8,500)	Hold
Marysville High	Soffits.	\$	(9)		Hold
McKenney Intermediate	ADA compliant renovation for entire campus.	\$	30	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to	Hold
McKenney Intermediate	ADA compliant sinks at permanent classrooms.	\$	ã)	follow in fall/winter 2017. Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
McKenney Intermediate McKenney Intermediate	Enclose ground-level units for student safety. Fire alarm components upgrade.	\$	5,000.00 15,000.00	The state of the s	Hold Hold
Olivehurst Elementary	ADA compliance throughout campus at older buildings.	\$	and the second	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Ollvehurst Elementary	ADA compliant renovation of restrooms.	\$	43	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Olivehurst Elementary	ADA hardware and doors on older buildings.	\$,ST	Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
				Cost dependent upon District ADA study. Site visits to take place in summer 2017.	

Yuba Feather Elementary	ADA compliant renovation of restrooms (including in existing classroom building and admin office area).	\$		Cost dependent upon District ADA study. Site visits to take place in summer 2017, Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Yuba Feather Elementary	ADA hardware and doors at older classrooms buildings.	\$		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Yuba Feather Elementary	Data bandwidth expansion needed.	\$		Bandwidth expansion needed; working with AT&T to get total cost.	Hold
Yuba Feather Elementary	Demolish and replace older restroom building, currently closed for use, or major renovation needed.	\$ =		Major facilities project; would need full design to determine cost.	Hold
Yuba Feather Elementary	Demolish tile/walls of older restroom building (If not replaced).	\$ 4,500.00			Hold
Yuba Feather Elementary	Drinking fountains,	\$ 6,000.00			Hold
Yuba Feather Elementary	Exhaust fans (throughout student restrooms).	\$ 11,000.00			Hold
Yuba Feather Elementary	Interior lighting of older restroom building (if not replaced).	\$ 1,200.00			Hold
Yuba Feather Elementary	Ramps and rails at portable classrooms.	\$ -		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Mold
Yuba Feather Elementary	Replace all old sinks and fixtures of older restroom building (If not replaced).	\$ 5,000.00		-	Hala
Yuba Feather Elementary	Room and building signage with Braille.	\$ -		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Yuba Feather Elementary	Tollet partitions of older restroom building (if not replaced).	\$ 3,800.00	TBD	Site is using the area for storage, This project is on hold until further notice,	Hold
Yuba Gardens Intermediate	ADA compliant renovation of restrooms.	\$		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Yuba Gardens Intermediate	ADA sinks and hardware needed at kitchen/cafeteria.	\$		Cost dependent upon District ADA study. Site visits to take place in summer 2017, Report with findings and cost estimates to follow in fall/winter 2017.	Hold
Yuba Gardens Intermediate	Fire alarm components upgrade.	\$ 15,000.00			Hold
Yuba Gardens Intermediate	Improve food service capabilities.	\$ =		Major facilities project; would need full design to determine cost.	Hold
Yuba Gardens Intermediate	New music room.	\$ =		Major facilities project; would need full design to determine cost.	Mold
Yuba Gardens Intermediate	Ramps and rails at portable classrooms.	\$ -		Cost dependent upon District ADA study. Site visits to take place in summer 2017. Report with findings and cost estimates to follow in fall/winter 2017.	Hold

		Non-FMP O	n Hold Buildings	& Grounds		
School Site	Project	Reason for Project Priority	Estimated Cost	Funding Source	Notes	Status
Linda Elementary	Re-landscape soccer field.	Safety	\$ 75,000.00	TBD	Renovate field with sod, add top soil and upgrade irrigation including a booster pump. We are waiting for a funding source to begin this project.	Hold
Lindhurst High	Install tankless water heater/ Culinary	Site request	\$ 5,800,00	Site	Site put on hold due to funding	On Hold/elts request
Lindhurst High	Phase 2 media room.	CTE grant; Improve program resources	\$ 80,000.00	TDB	On hold due to funding.	On Hold/site request
Lindhurst High	Front sliding gates.	Site request	\$ 32,000.00	тво	Getting estimate	Hotel
Lindhurst High	Camera upgrades and repairs,	Safety	\$ 135,000.00	TBD	Replace 32 analog cameras with digital cameras. Replace 30 non-functioning cameras. Waiting on update from Tech Services.	Holid
Lindhurst High	HVAC phase (formerly increment) #3.	Failing system; safety issue	\$ 2,000,000.00	General Fund - One-Time Discretionary	On Hold. System is working now that there is less load on the chiller.	Helif
Lindhurst High	HVAC phase (formerly increment) #4.	Falling system; safety issue	\$ 4,000,000.00	On Hold	On Hold. System is working now that there is less load on the chiller.	Mahit
Lindhurst High	HVAC phase 3 design - increment #s 3 and 4.	Safety	\$ 236,250.00	General Fund - One-Time Discretionary	On Hold. System is working now that there is less load on the chiller.	Helii
Marysville High	Re-landscape lawn area by field house.	Curb Appeal	\$ 3,000.00	TBD	Re-sod, add drip irrigation system and three trees. On hold due to potential solar project.	Hald
Marysville High	Re-landscape football field.	Safety	\$ 150,000.00	TBD	Field is in playable condition. There are no immediate safety concerns with the field.	Hald
MCAA	Ventilation/cooling for main office IT room.	Add ventilation to IT room in main office.	\$ 1,800.00	TBD	Maintenance will address as time allows.	thelif